

Photo#1:

View of Location entry looking out to County Road. Inserts are detail of Toadflax at either side of Gates.



June 15, 2017



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Encana PA Carpenter API#077-08454

Photo#2:

View to NE over field area of sparse growth and bare ground.



June 15, 2017



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Encana PA Carpenter API#077-08454

Photo#3:

Views to SE of problem areas of spotty revegetation in Location.

Photo#4:



June 15, 2017



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Encana PA Carpenter API#077-08454

Photo#5:

Photo#6:

A few Scotch Thistle, Canada thistle and Toadflax plants noted in field area of Location.



June 15, 2017

Photo#7:

Difference in color height & density of vegetation is easily noticeable across Location



June 15, 2017



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Encana PA Carpenter API#077-08454