

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/14/2017

Submitted Date:

06/19/2017

Document Number:

674603382

FIELD INSPECTION FORM

Loc ID 319664 Inspector Name: Maclaren, Joe On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10548
Name of Operator: HRM RESOURCES II LLC
Address: 410 17TH STREET #1600
City: DENVER State: CO Zip: 80202

Findings:

- 2 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Prohaska, April	303-893-6621	aprohaska@hrmres.com	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
Pape, Terry	303-893-6621	tpape@hrmres.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
200774	WELL	SI	03/01/2017	GW	001-06177	RANDALL 41-10	EG

General Comment:

[2017 Flowline NTO Inspection 1000' Buffer; Witnessing removal of flowline risers and out of service flowline abandonments.](#)

Inspected FacilitiesFacility ID: 200774 Type: WELL API Number: 001-06177 Status: SI Insp. Status: EG**Flowline**

#1	Type:	of Lines	
<u>Flowline Description</u>			
Flowline Type:	Size:	Material: <u>Carbon Steel</u>	
Variance:	Age:	Contents:	
<u>Integrity Summary</u>			
Failures:	Spills:	Repairs Made:	
Coatings:	H2S:	Cathodic Protection:	
<u>Pressure Testing</u>			
Witnessed:	Test Result:	Charted:	
<u>COGCC Rules(check all that apply)</u>			
<input type="checkbox"/> 1101. Installation and Reclamation <input type="checkbox"/> 1102. Operations, Maintenance, and Repair <input checked="" type="checkbox"/> 1103. Abandonment			
Comment:	HRM contractor (Shorty's) in process of removing unused flowline risers (previously identified and marked with fluorescent paint) and abandoning short sections of unused process piping flowlines at the Randall 41-10 and 32-10 facility/ battery; per COGCC Flowline NTO.		
Corrective Action:			Date:

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401311896	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4174032
674603389	Battery and signage	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4174021
674603390	Unused risers being removed near treater	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4174023
674603392	Unused risers removed per NTO	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4174024