

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/19/2017

Submitted Date:

06/19/2017

Document Number:

685303390**FIELD INSPECTION FORM**Loc ID 333036 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 100264Name of Operator: XTO ENERGY INCAddress: PO BOX 6501City: ENGLEWOOD State: CO Zip: 80155**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Hixon, Logan	505-386-8018	logan_hixon@xtoenergy.com	SW EHS Tech
Woolley, Jeff	505-333-3222	Jeff_Woolley@xtoenergy.com	SW Inspection Reports
Trobaugh, Robert	505-333-3185	robert_trobaugh@xtoenergy.com	SW Inspection Reports

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214789	WELL	PR	10/23/2003	GW	067-06393	MCDONALD C 1	PR

General Comment:[2017 Flowline NTO Inspection 1000' Buffer](#)[Shadowing Operator Pressure Testing Team](#)[Retest of Fruitland Coal wellhead tubing to separator inlet.](#)

Inspected FacilitiesFacility ID: 214789 Type: WELL API Number: 067-06393 Status: PR Insp. Status: PR**Flowline**

#1 Type: Well Site 1 of Lines

Flowline DescriptionFlowline Type: Well Site Size: 3" Material: Carbon Steel
Variance: Age: Contents: Natural GasIntegrity SummaryFailures: Spills: Repairs Made: Yes
Coatings: H2S: Cathodic Protection:Pressure TestingWitnessed: Yes Test Result: Pass Charted: YesCOGCC Rules(check all that apply)☐ 1101. Installation and Reclamation ☒ 1102. Operations, Maintenance, and Repair ☐ 1103. AbandonmentComment: Witnessed retest of flow line pressure test on steel gas line from wellhead Fruitland Coal tubing to separator inlet. Operator completed repairs replacing two baylon vaves on wellhead tree. All points are on location. 37.02751/-107.54599 from Scout Card. Testing was part of requirement of May 2, 2017 NTO. Test was conducted using Crystal gauge for pressure reading and charting. Starting pressure was 59.8 psi and ending pressure was 60.1 psi. Test duration was 15 minutes.

Corrective Action:

Date:

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401313118	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4174922
685303393	Wellhead sign.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4174872