

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/19/2017

Submitted Date:

06/19/2017

Document Number:

685303392**FIELD INSPECTION FORM**Loc ID 306779 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 100264Name of Operator: XTO ENERGY INCAddress: PO BOX 6501City: ENGLEWOOD State: CO Zip: 80155**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**6 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Hixon, Logan	505-386-8018	logan_hixon@xtoenergy.com	<a href="#">SW EHS Tech</a>
Woolley, Jeff	505-333-3222	Jeff_Woolley@xtoenergy.com	<a href="#">SW Inspection Reports</a>
Trobaugh, Robert	505-333-3185	robert_trobaugh@xtoenergy.com	<a href="#">SW Inspection Reports</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
264621	WELL	PR	11/21/2002	GW	067-08746	ANDERSON 1 (1R)	PR

**General Comment:**[2017 Flowline NTO Inspection 1000' Buffer](#)[Witness Flowline Abandonment](#)

**Location**Overall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Flow Line	#		corrective date
Comment:	1" steel line previously used for domestic tap was dug up, cut off below grade and capped. Stub above ground was pulled and hole back filled to complete work. Capped end of line 37.024921/-107.31779 taken with Garmin.		
Corrective Action:			Date:

**Venting:**

Yes/No		
Comment:		
Corrective Action:		Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 264621 Type: WELL API Number: 067-08746 Status: PR Insp. Status: PR

**Flowline**

#1	Type: Well Site	1 of Lines
----	-----------------	------------

Flowline Description

Flowline Type: Well Site Size: Other Material: Carbon Steel  
 Variance: Age: Contents: Natural Gas

Integrity Summary

Failures: Spills: Repairs Made:  
 Coatings: H2S: Cathodic Protection:

Pressure Testing

Witnessed: Test Result: Charted:

COGCC Rules(check all that apply)

☐ 1101. Installation and Reclamation ☐ 1102. Operations, Maintenance, and Repair ☒ 1103. Abandonment

Comment: 1" steel line previously used for domestic tap was dug up and cut off below grade. Line end was threaded and capped. The remaining above ground stub was then pulled and the hole back filled to complete work. Capped end of line 37.024921/-107.31779 taken with Garmin.

Corrective Action: Date:

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401313120	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4174924">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4174924</a>
685303394	Wellhead sign.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4174873">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4174873</a>
685303395	1" gas line stub to be removed.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4174874">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4174874</a>
685303396	Capped end of line before backfill.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4174875">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4174875</a>
685303397	Completed backfill.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4174876">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4174876</a>