

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/13/2017

Submitted Date:

06/19/2017

Document Number:

687900038**FIELD INSPECTION FORM**

Loc ID 309162 Inspector Name: DURAN, JOHN On-Site Inspection ☐ 2A Doc Num:

Operator Information:OGCC Operator Number: 100264Name of Operator: XTO ENERGY INCAddress: PO BOX 6501City: ENGLEWOOD State: CO Zip: 80155**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:13 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Harrison, Lyndon	505-333-3100	Lyndon_Harrison@xtoenergy.com	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
Trujillo, Irwin	719-846-0272/719-859-2264	irwin_trujillo@xtoenergy.com	Sr. Env. Tech., Raton Basin
Fitzgerald, Edie	719-845-2108/719-859-1394	Edie_Fitzgerald@xtoenergy.com	Env. Tech, Raton Basin

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
289043	WELL	PR	05/09/2008	GW	071-09185	GOLDEN EAGLE 20-13	PR

General Comment:

2017 Flowline NTO Inspection
 Shadowing Operator Pressure Testing Team
 XTO Team : Joseph Garcia, Carl Vialpando, and Joe Amato

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date:

Overall Good: ☒

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Flow Line	# 1		
Comment:	IN USE : 1 - 2" Fuel/Gas line riser at separator (37.15394/-104.91415).		
Corrective Action:		Date:	
Type: Flow Line	# 1		
Comment:	IN USE : 1 - 4" Casing line riser at wellhead (37.15393/-104.91432).		
Corrective Action:		Date:	
Type: Flow Line	# 1		
Comment:	IN USE : 1 - 3" Tubing line riser at separator (37.15394/-104.91415) to pit.		
Corrective Action:		Date:	
Type: Flow Line	# 1		
Comment:	IN USE : 1 - 3" Tubing line riser at wellhead (37.15393/-104.91432) to separator.		
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 289043 Type: WELL API Number: 071-09185 Status: PR Insp. Status: PR

Flowline

#1	Type: Well Site	1 of Lines
----	-----------------	------------

Flowline Description

Flowline Type: Well Site Size: 3" Material: Poly
 Variance: Yes Age: 5-10 Yrs Contents: Produced Water

Integrity Summary

Failures: Spills: No Repairs Made: No
 Coatings: Yes External H2S: No Cathodic Protection: No

Pressure Testing

Witnessed: Yes Test Result: Pass Charted: Yes

COGCC Rules(check all that apply)

☐ 1101. Installation and Reclamation ☒ 1102. Operations, Maintenance, and Repair ☐ 1103. Abandonment

Comment: Material : Carbon Steel riser to Poly line. No physical chart in the field, but XTO used a Crystal Digital Pressure Guage - AMETEK xpzi 5,000 psig (To record pressures). Time : 4:19 pm, P=20.7 psig, Time : 4:34 pm, P=20.5 psig.

Corrective Action:

Date:

#2	Type: Well Site	1 of Lines
----	-----------------	------------

Flowline Description

Flowline Type: Well Site Size: 3" Material: Poly
 Variance: Yes Age: 5-10 Yrs Contents: Produced Water

Integrity Summary

Failures: Spills: No Repairs Made: No
 Coatings: Yes External H2S: No Cathodic Protection: No

Pressure Testing

Witnessed: Yes Test Result: Pass Charted: Yes

COGCC Rules(check all that apply)

☐ 1101. Installation and Reclamation ☐ 1102. Operations, Maintenance, and Repair ☐ 1103. Abandonment

Comment: Material : Carbon Steel riser to Poly line. No physical chart in the field, but XTO used a Crystal Digital Pressure Guage - AMETEK xpzi 5,000 psig (To record pressures). Time : 5:04 pm, P=5.6 psig, Time : 5:19 pm, P=5.5 psig.

Corrective Action:

Date:

#3	Type: Well Site	1 of Lines
----	-----------------	------------

Flowline Description

Flowline Type: Well Site Size: 4" Material: Poly
 Variance: No Age: 5-10 Yrs Contents: Natural Gas

Integrity Summary

Failures: Spills: No Repairs Made: No
 Coatings: Yes External H2S: No Cathodic Protection: No

Pressure Testing

Witnessed: YesTest Result: PassCharted: NoCOGCC Rules(check all that apply)☐ 1101. Installation and Reclamation☒ 1102. Operations, Maintenance, and Repair☐ 1103. AbandonmentComment:

Material : Carbon Steel riser to Poly line. No physical chart in the field, but XTO used a Crystal Digital Pressure Guage - AMETEK xpzi 5,000 psig (To record pressures). Pressure Guage was malfunctioning(Would not zero out). Had to use liquid guage. Team says they will do over. Time : 5:35 pm, P=4.0 psig, Time : 5:50 pm, P=4.1 psig.

Corrective Action:

Date:

#4 Type: Well Site

1 of Lines

Flowline DescriptionFlowline Type: Well SiteSize: 2"Material: PolyVariance: NoAge: 5-10 YrsContents: Natural GasIntegrity Summary

Failures:

Spills: NoRepairs Made: NoCoatings: Yes ExternalH2S: NoCathodic Protection: NoPressure TestingWitnessed: YesTest Result: PassCharted: YesCOGCC Rules(check all that apply)☐ 1101. Installation and Reclamation☒ 1102. Operations, Maintenance, and Repair☐ 1103. AbandonmentComment:

Material : Carbon Steel riser to Poly line. No physical chart in the field, but XTO used a Crystal Digital Pressure Guage - AMETEK xpzi 5,000 psig (To record pressures). Time : 5:58 PM, P=3.1 psig, Time : 6:13 pm, P=2.9 psig.

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PITType: Produced WaterLined: NOPit ID: Lat: Long: Reference Point: Other: Length: Width: **Lining:**Liner Type: Liner Condition: Comment: Corrective Action: Date: c**Fencing:**Fencing Type: Fencing Condition: Comment: Corrective Action: Date: **Netting:**Netting Type: Netting Condition: Comment: Corrective Action: Date: Anchor Trench Present: Oil Accumulation: NO2+ feet Freeboard: YESComment: 30' x 70'Corrective Action: Date: Monitoring: Monitoring Type: Comment: Other:

Blue stake

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401311643	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4173854