

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/09/2017

Submitted Date:

06/19/2017

Document Number:

688000018

FIELD INSPECTION FORM

Loc ID 317269 Inspector Name: YOUNG, ROB On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 82470
Name of Operator: STELBAR OIL CORP INC
Address: 1625 N WATERFRONT PKWY #200
City: WICHITA State: KS Zip: 67206-

Findings:

- 2 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
104548	PIT	AC			-	MATHIES 1-13	EI

General Comment:

[Environmental inspection related to NORM project EDB #755550 sampling.](#)

Inspected Facilities

Facility ID: 104548 Type: PIT API Number: - Status: AC Insp. Status: EI

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: Produced Water Lined: NO Pit ID: 104548 Lat: 39.875170 Long: -102.934509

Reference Point: SE Other: _____ Length: 40 Width: 40

Lining:

Liner Type: _____ Liner Condition: _____

Comment: Pit was dry and in satisfactory condition.

Corrective Action

Date: c

Fencing:

Fencing Type: _____ Fencing Condition: _____

Comment:

Corrective Action

Date: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment:

Corrective Action

Date: _____

Anchor Trench Present: _____ Oil Accumulation: _____ 2+ feet Freeboard: _____

Comment:

Corrective Action

Date: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401311968	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4174070
688000024	EDB #755550 Sampling Location Photograph	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4174066