

# Inspection Photos

6/23/2017

Operator: GRAND MESA OPERATING CO - 35080

Location ID: 450631

Inspection Doc. Number: 682502323

Washington County, CO

Aaron Trujillo

Reclamation Specialist

COGCC



Inspection Photos  
Operator: GRAND MESA OPERATING CO -  
35080  
Location ID: 450631



**Photo 1:** Photo taken from the southwest end of the location, facing north. Photo shows topsoil stockpiles on the west end of the location. Photo also shows perimeter stormwater and sediment BMP controls have not been implemented.



**Photo 2:** Photo taken from the southwest end of the location, facing east.

Inspection Photos  
Operator: GRAND MESA OPERATING CO -  
35080  
Location ID: 450631



**Photo 3:** Photo taken from the west end of the location. Photo shows topsoil stockpiles on the west end of the location. Photo also shows perimeter stormwater and sediment BMP controls have not been implemented.



**Photo 4:** Photo taken from the west end of the location. Photo shows topsoil piles have been insufficiently tracked.

Inspection Photos  
Operator: GRAND MESA OPERATING CO -  
35080  
Location ID: 450631



**Photo 5:** Photo taken from the northwest end of the location, facing south. Photo shows topsoil stockpiles on the west end of the location . Photo also shows perimeter stormwater and sediment BMP controls have not been implemented.



**Photo 6:** Photo taken from the northwest end of the location, facing east. Photo shows perimeter stormwater and sediment BMP controls have not been implemented.

Inspection Photos  
Operator: GRAND MESA OPERATING CO -  
35080  
Location ID: 450631



**Photo 7:** Photo taken from the north end of the location, facing southwest. Photo shows perimeter stormwater and sediment BMP controls have not been implemented.



**Photo 8:** Photo taken from the north end of the location, facing south. Photo shows perimeter stormwater and sediment BMP controls have not been implemented.

Inspection Photos  
Operator: GRAND MESA OPERATING CO -  
35080  
Location ID: 450631



**Photo 9:** Photo taken from the north end of the location, facing east. Photo shows berm that appears to be sufficiently consolidated.



**Photo 10:** Photo taken from the northeast end of the location, facing west. Photo shows berm that appears to be sufficiently consolidated.

Inspection Photos  
Operator: GRAND MESA OPERATING CO -  
35080  
Location ID: 450631



**Photo 11:** Photo taken from the northeast end of the location, facing south. Photo shows berm constructed on the eastern perimeter of the location. Berm has not been constructed with good engineering practices; berm has not been sufficiently consolidated and not in proper functioning conduction.



**Photo 12:** Photo taken from the northeast end of the location, facing south. Photo shows berm constructed on the eastern perimeter of the location. Berm has not been constructed with good engineering practices; berm has not been sufficiently consolidated and not in proper functioning conduction.

Inspection Photos  
Operator: GRAND MESA OPERATING CO -  
35080  
Location ID: 450631



**Photo 13:** Photo taken from the north end of the location, facing south. Photo shows berm constructed on the eastern perimeter of the location. Berm has not been constructed with good engineering practices; berm has not been sufficiently consolidated and not in proper functioning conduction.




**Photo 14:** Photo taken from the southeast end of the location, facing north. Photo shows berm constructed on the eastern perimeter of the location. Berm has not been constructed with good engineering practices; berm has not been sufficiently consolidated and not in proper functioning conduction.

Inspection Photos  
Operator: GRAND MESA OPERATING CO -  
35080  
Location ID: 450631



**Photo 15:** Photo taken from the southeast end of the location, facing west. Photo shows equipment being stored off location. Access road (yellow line) appears to straddle the North and Southern 1/2 of section 30. Washington County Assessor indicated that the North half of section 30 is owned by the surface owners listed in the 2A, however the southwest 1/4 of section 30 is listed under a surface owner not on the 2A. It appears operator is parking equipment/disturbing a separate surface owner's property. This issue is being forwarded to OGLA



**Photo 16:** Photo taken from the access road, west of the location, facing east. Photo shows rock material used as a tracking pad. Access road (yellow line) appears to straddle the North and Southern 1/2 of section 30. Washington County Assessor indicated that the North half of section 30 is owned by the surface owners listed in the 2A, however the southwest 1/4 of section 30 is listed under a surface owner not on the 2A. It appears operator is parking equipment/disturbing a separate surface owner's property. This issue is being forwarded to OGLA

Inspection Photos  
Operator: GRAND MESA OPERATING CO -  
35080  
Location ID: 450631



**Photo 17:** Photo taken from the southeast of the location, facing north west. Photo shows equipment and vehicles parked off location. Yellow line indicates the approximate border between the North and Southern ½ of section 30. Washington County Assessor indicated that the North half of section 30 is owned by the surface owners listed in the 2A, however the southwest ¼ of section 30 is listed under a surface owner not on the 2A. It appears operator is parking equipment/disturbing a separate surface owner's property. This issue is being forwarded to OGLA



**Photo 18:** Photo taken from the southeast of the location, facing north. Yellow line indicates the approximate border between the North and Southern ½ of section 30. Washington County Assessor indicated that the North half of section 30 is owned by the surface owners listed in the 2A, however the southwest ¼ of section 30 is listed under a surface owner not on the 2A. It appears operator is parking equipment/disturbing a separate surface owner's property. This issue is being forwarded to OGLA