

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/14/2017

Submitted Date:

06/20/2017

Document Number:

673715605**FIELD INSPECTION FORM**
 Loc ID 435948 Inspector Name: Sherman, Susan On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 26580Name of Operator: BURLINGTON RESOURCES OIL & GAS LPAddress: PO BOX 4289City: FARMINGTON State: NM Zip: 87499**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:9 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Gahr, Dean	(303) 268-3723	Dean.P.Gahr@conocophillips.com	All DJ Basin Inspections
Strickler, Robert		Robert.D.Strickler@conocophillips.com	All DJ Basin Inspections
Prasanna, Sonu	832-486-2299	sonu.prasanna@conocophillips.com	Regulatory Supervisor
Aldrich, Brian	307-240-1882	Brian.C.aldrich@conocophillips.com	Production

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
435946	WELL	PR	12/02/2014	OW	005-07217	Grimm Motocross 4-65 23-24 1H	EG
435947	WELL	PR	12/02/2014	OW	005-07218	Sunset 4-65 21-22 1H	EG

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 855-595-8258

Corrective Action:

Date: _____

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Flow Line	#		
Comment:	Underground flowlines are from well to treater, from well to compressor and from compressor to flare for each well. All other processing lines are above ground. Conoco has as built drawings for each location. At compressor there are 2-2" fiberspar lines GPS 39.66725, -104.11816 and 39.66725, -104.11816.		
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:	On storage tank at compressor.		
Corrective Action:		Date:	

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	

Corrective Action:		Date:	
--------------------	--	-------	--

Inspected FacilitiesFacility ID: 435946 Type: WELL API Number: 005-07217 Status: PR Insp. Status: EGFacility ID: 435947 Type: WELL API Number: 005-07218 Status: PR Insp. Status: EG**Producing Well**

Comment:

Corrective Action:

Date:

BradenHeadComment: Grimm 1 psi, Sunset 2 psi

Corrective Action:

Date:

Flowline

#1 Type: Process Piping

of Lines

Flowline DescriptionFlowline Type: Process Piping

Size:

Material: OtherVariance: Yes

Age:

Contents:

Integrity Summary

Failures:

Spills:

Repairs Made:

Coatings:

H2S:

Cathodic Protection:

Pressure TestingWitnessed: YesTest Result: PassCharted: Yes**COGCC Rules(check all that apply)**☐ 1101. Installation and Reclamation☒ 1102. Operations, Maintenance, and Repair☐ 1103. Abandonment

Comment:

Lynn Coffman with Conoco was on location testing treater to compressor lines. Conoco has waiver for alternate testing on above ground piping that initially did not meet the requirements of the Flowline NTO, however, after further review the waivers were accepted by COGCC for the NTO. Wells SI for testing. Two separate Crystal gauges-one for each well. Material of flowline Fiberspar. Grimm 54/53 psi and Sunset 53/47 psi compressor to well test. Flowline pressures at wellheads were 62 psi on Grimm and 78 psi on Sunset during testing. On 6/15/2017 inspector met with Conoco representative on site for testing of vent lines with 14 oz of psi to combustors. The "Skillet" method was used (ASTM).

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401313787	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4175633
673715630	Conoco Grimm Motocross and Sunset	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4175603