

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

06/12/2017

Submitted Date:

06/20/2017

Document Number:

674901750**FIELD INSPECTION FORM**
 Loc ID 417386 Inspector Name: Hughes, Jim On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 5Name of Operator: COLORADO OIL & GAS CONSERVATIONAddress: 1120 LINCOLN ST SUITE 801City: DENVER State: CO Zip: 80203**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:7 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
417389	WELL	AC	06/10/2015	GW	007-06293	DEEP CANYON MW 34-4-32-1	EI

General Comment:

On June 12, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the COGCC Deep Canyon MW 34-4-32 #1. For the most recent field inspection report of this facility, please refer to document #674901156. The purpose of this site visit was to replace the desiccants, which was last completed on 6/9/16.

LocationOverall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:	Sign mounted to stock panel enclosure.		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	Sign mounted to stock panel enclosure.		
Corrective Action:		Date:	

Overall Good: ☒

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Stock panel enclosure		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Ancillary equipment	# 1		
Comment:	Telemetry		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	In-Situ data logger		
Corrective Action:		Date:	

Venting:			
Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	417389	Type:	WELL	API Number:	007-06293	Status:	AC	Insp. Status:	EI

--

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action: Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
On June 12, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the COGCC Deep Canyon MW 34-4-32 #1. For the most recent field inspection report of this facility, please refer to document #674901156. The purpose of this site visit was to replace the desiccants, which was last completed on 6/9/16. During this inspection the eight desiccant packets and the Desi-Tube were replaced. The three lead acid batteries were in good condition with no signs of corrosion.	hughesj	06/20/2017

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401313091	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4174899
674901751	Deep Canyon MW 34-4-32 #1 location photo.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4174856
674901752	Deep Canyon MW 34-4-32 #1 equipment enclosures.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4174857