

FORM
INSPRev
X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/12/2017

Submitted Date:

06/20/2017

Document Number:

674901761

FIELD INSPECTION FORM

Loc ID 306806 Inspector Name: Hughes, Jim On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 5
 Name of Operator: COLORADO OIL & GAS CONSERVATION
 Address: 1120 LINCOLN ST SUITE 801
 City: DENVER State: CO Zip: 80203

Findings:

7 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
267716	WELL	AC	02/14/2003	OBW	067-08805	MONITOR WELL 35-6-13-1	EI

General Comment:

On June 12, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the COGCC Shamrock Mine MW 35-6-13 #1. For the most recent field inspection report of this facility, please refer to document # 674901289. The purpose of this site visit was to replace the desiccants in the equipment enclosures.

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	Sign mounted to protective steel cage surrounding well head.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:
 Corrective Action:
 Date: _____

Overall Good:

Spills:

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:	Locked 4' x 4' x 4' expanded metal and angle iron protective cage surrounding well head.		
Corrective Action:		Date:	

Equipment:

Type: Ancillary equipment	# 1		corrective date
Comment:	In-Situ data logger.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Telemetry.		
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 267716 Type: WELL API Number: 067-08805 Status: AC Insp. Status: EI

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>On June 12, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the COGCC Shamrock Mine MW 35-6-13 #1. For the most recent field inspection report of this facility, please refer to document # 674901289. The purpose of this site visit was to replace the desiccants in the equipment enclosures. The battery terminals on the solar back up batteries and the battery in the Troll Link 201 enclosure are clean and free of any corrosion. Eight desiccant packets and the Desi-tube were replaced during this site visit. These were last replaced on 9/7/16.</p>	hughesj	06/20/2017

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401313333	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4175175
674901762	Shamrock Mine well head w/ protective cage.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4175169
674901763	Shamrock Mine equipment enclosures.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4175170