

FORM
INSPRev
X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/12/2017

Submitted Date:

06/20/2017

Document Number:

674901764

FIELD INSPECTION FORM

Loc ID 334385 Inspector Name: Hughes, Jim On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 5
 Name of Operator: COLORADO OIL & GAS CONSERVATION
 Address: 1120 LINCOLN ST SUITE 801
 City: DENVER State: CO Zip: 80203

Findings:

7 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
267693	WELL	AC	06/15/2015	OBW	067-08802	MONITOR WELL 35-6-17-1	EI
267867	WELL	AC	06/15/2015	OBW	067-08814	MONITOR WELL 35-6-17-2	EI

General Comment:

On June 12, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the COGCC Beaver Creek Ranch MW 35 -6-17 #1 and #2. For the most recent field inspection report for this facility, please refer to document #674901228. The purpose of this site visit was to replace desiccants in the equipment enclosures and troubleshoot the telemetry system.

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	Sign mounted to angle iron and expanded metal protective cages.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	Sign mounted to metal shack housing ancillary equipment.	Date:	
Corrective Action:			

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:	4' x 4' x 4' expanded metal and angle iron protective cages surrounding well heads.		
Corrective Action:		Date:	

Equipment:

Type: Ancillary equipment	# 1		corrective date
Comment:	In-Situ data logger.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Telemetry.		
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 267693 Type: WELL API Number: 067-08802 Status: AC Insp. Status: EI

Facility ID: 267867 Type: WELL API Number: 067-08814 Status: AC Insp. Status: EI

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>On June 12, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the COGCC Beaver Creek Ranch MW 35-6-17 #1 and #2. For the most recent field inspection report for this facility, please refer to document #674901228. The purpose of this site visit was to replace desiccants in the equipment enclosures and troubleshoot the telemetry system.</p> <p>During this inspection eight desiccant packets and one Desi-tube were replaced. This was last completed on 5/23/16.</p> <p>This station had stopped reporting data. Upon further investigation, one of the fuses in the TL 201 enclosure had blown. The right fuse in this equipment enclosure was replaced and was functioning properly.</p> <p>All of the three batteries at this site were at 13.76 V.</p>	hughesj	06/20/2017

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401313393	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4175207
674901765	Beaver Creek Ranch TL 201 enclosure.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4175205
674901766	TL 201 enclosure w/ new fuse and desiccants.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4175206