

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/19/2017

Submitted Date:

06/20/2017

Document Number:

679700529

**FIELD INSPECTION FORM**

Loc ID 333069 Inspector Name: ALLISON, RICK On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10459  
Name of Operator: EXTRACTION OIL & GAS INC  
Address: 370 17TH STREET SUITE 5300  
City: DENVER State: CO Zip: 80202

**Findings:**

- 8 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Inspections, COGCC		COGCCInspections@extracti onog.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
245403	WELL	PR	02/01/2017	GW	123-13198	WINTER 15-19	EI
448567	TANK BATTERY	AC			-	Winters Battery	EI

**General Comment:**

COGCC Environmental Staff Inspection, Extraction is abandoning the Winter 10,15-19 tank battery and preparing site for abandonment. See inspection #679700530 for Tigges Winter 15-19-0 inspection.

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

<b>Spills:</b>					
Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Equipment:</b>				corrective date
Type: Gas Meter Run	# 1			
Comment: Gas meter present on location at 40.46470,-104.59097				
Corrective Action:				Date:
Type: Flow Line	#			
Comment: Field crew is onsite dismantling production equipment. Wellhead and separation equipment have been disconnected from flowlines. Flowlines must be abandoned per Rule 1103 and the Flowline Guidance Document.				
Corrective Action:				Date:
Type: Horizontal Heated Separator	# 1			
Comment: Separator is disconnected. Field crew on location abandoning tank battery.				
Corrective Action:				Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	BV CONCRETE		
Comment: Field crew is preparing site for abandonment. Partially buried vessel is adjacent the Tigges 15-19-0 tank battery. Abandonment of a buried produced water vessel requires the Operator to submit a Form 27 per Rule 905.b.					
Corrective Action:					Date:

**Paint**

Condition	<input type="text"/>
Other (Content)	<input type="text"/>
Other (Capacity)	<input type="text"/>
Other (Type)	<input type="text"/>

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS

CRUDE OIL	2	300 BBLs	STEEL AST		
Comment:	Field crew is present on location, emptying tanks and preparing site for abandonment and reclamation. Tanks are adjacent the Tigges Winter 15-19-0 tank battery				
Corrective Action:					Date:
<b>Paint</b>					
Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					
<b>Berms</b>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:
<b>Venting:</b>					
Yes/No					
Comment:					
Corrective Action:					Date:
<b>Flaring:</b>					
Type					
Comment:					
Corrective Action:					Date:

**Inspected Facilities**Facility ID: 245403 Type: WELL API Number: 123-13198 Status: PR Insp. Status: EIFacility ID: 448567 Type: TANK API Number: - Status: AC Insp. Status: EI**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401313239	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4175121">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4175121</a>
679700535	Extraction buried produced water vessel	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4175105">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4175105</a>
679700536	Separator and meter shed	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4175106">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4175106</a>
679700537	Wellhead disconnected from flowlines	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4175107">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4175107</a>