

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/19/2017

Submitted Date:

06/20/2017

Document Number:

679700530

FIELD INSPECTION FORM

Loc ID 333069 Inspector Name: ALLISON, RICK On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 88265
Name of Operator: TIGGES OIL LLC
Address: 12406 WCR 64 1/2
City: GREELEY State: CO Zip: 80631

Findings:

- 6 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Axelson, John		john.axelson@state.co.us	
Mah, Steven		steven.mah@state.co.us	
Kenneth Tigges	970-686-2836	oakleylee@msn.com	
Levi Tigges		levi.tigges@gmail.com	
Jesse Tigges		jesse.tigges@gmail.com	
Gomez, Jason		jason.gomez@state.co.us	
Binschus, Chris		chris.binschus@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
245942	WELL	PA	12/08/2014	OW	123-13737	WINTER 15-19-0	EI
451121	TANK BATTERY	AC			-	Winter 15-19-0 Tank Battery	EI

General Comment:

[COGCC Environmental Staff Inspection, Extraction is abanonding the adjacent Winter 10,15-19 tank battery. See inspection #679700529 for Extraction Winter 10,15-19 inspection. This inspection pertains to the Tigges Winter 15-19-0 location only.](#)

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type: UNUSED EQUIPMENT

Comment:

Corrective Action:

Date: 03/10/2015

Overall Good:

Spills:

Type	Area	Volume
Crude Oil	Tank	

Crude Oil: Tank

Comment:

Corrective Action:

Date: 06/30/2017

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

corrective date

Type: Flow Line # 1

Comment:

Corrective Action:

Date: 06/30/2017

Venting:

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 245942 Type: WELL API Number: 123-13737 Status: PA Insp. Status: EI

Facility ID: 451121 Type: TANK API Number: - Status: AC Insp. Status: EI

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____
 1003c. Compacted areas have been cross ripped? _____
 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
 Cuttings management: _____
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
 Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA% _____
 TRANSECT RESULTS OF REFERENCE AREA% _____
 TOTAL % OF DESIRABLE VEGETATION COVER _____
 VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment

Corrective Action

Date _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment:

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA% _____
 TRANSECT RESULTS OF REFERENCE AREA% _____
 TOTAL % OF DESIRABLE VEGETATION COVER _____
 VEGETATIVE COVER _____

Comment:

Corrective Action:

Date _____

Overall Final Reclamation _____ Well Release on Active Location Multi-Well Location

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401313241	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4175122
679700538	Tank Battery Sign	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4175108
679700539	Tigges tank battery in foreground	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4175109
679700540	Broken valve on AST	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4175110
679700541	Corrosion on produced water AST	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4175111
679700542	Corrosion on produced water AST	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4175112
679700543	Damage to produced water AST	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4175113
679700544	flowline riser at produced water ASTs	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4175114