

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/14/2017

Submitted Date:

06/20/2017

Document Number:

680302027

**FIELD INSPECTION FORM**

Loc ID 304871 Inspector Name: SCHURE, KYM On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 75027  
Name of Operator: ROSEWOOD RESOURCES INC  
Address: 2101 CEDAR SPRINGS RD STE 1500  
City: DALLAS State: TX Zip: 75201

**Findings:**

- 9 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Krehmeyer, James	970-848-2228	jkrehmeyer@rosewd.com	Cell # 970-630-3880

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
275663	WELL	PR	04/12/2005	GW	125-09088	MONK 4-7	PR

**General Comment:**

Routine Site Inspection

**Location**

**Lease Road:**

Type	Access				
comment:	Satisfactory Located within rotational cropland				
Corrective ActionL					Date:

Overall Good:

**Signs/Marker:**

Type	WELLHEAD				
Comment:	Satisfactory				
Corrective Action:					Date:

Emergency Contact Number:

Comment:	Satisfactory				
Corrective Action:					Date: _____

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment: \_\_\_\_\_

Multiple Spills and Releases?

**Fencing/:**

Type	WELLHEAD				
Comment:	Steel panel				
Corrective Action:					Date:

**Equipment:**

					corrective date
Type: Prime Mover	# 1				
Comment:	Flowing GW				
Corrective Action:					Date:
Type: Gas Meter Run	# 1				
Comment:					
Corrective Action:					Date:
Type: Vertical Separator	# 1				
Comment:					
Corrective Action:					Date:

**Venting:**

Yes/No					
Comment:					
Corrective Action:					Date:

**Flaring:**

Type					
------	--	--	--	--	--

Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 275663 Type: WELL API Number: 125-09088 Status: PR Insp. Status: PR

**Producing Well**

Comment: [FGW](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	In Process	Other	In Process			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401313799	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4175645">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4175645</a>