

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/15/2017

Submitted Date:

06/27/2017

Document Number:

674603412**FIELD INSPECTION FORM**

Loc ID 307113 Inspector Name: Maclaren, Joe On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10312Name of Operator: PROSPECT ENERGY LLCAddress: 1036 COUNTRY CLUB ESTATES DRCity: CASTLE ROCK State: CO Zip: 80108**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
Twele, Megan		mtwele@progressivepcs.net	
Giltner, Ward		wgiltner@yahoo.com	
Gracey, Cameron		graceyservices@msn.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
216895	WELL	PR	09/20/2006	OW	069-06082	FT. COLLINS MUDDY UNIT 30-4	EG

General Comment:

COGCC Engineering Integrity Inspector met with Prospect Energy Field Manager Cam Gracey and performed a flowline (abandonment) field inspection. The MSSU 30-4 (API 069-06082) has been plugged and abandoned (Form 6 Intent Doc #2226144 received on 03/14/17). Details of observations made during this field inspection are available in the flowline section of this report. Photo's uploaded can be accessed via link(s) at end of report.

Inspected Facilities

Facility ID: 216895 Type: WELL API Number: 069-06082 Status: PR Insp. Status: EG

Flowline

#1	Type: Non-Well Site	2 of Lines	
----	---------------------	------------	--

Flowline Description

Flowline Type: Non-Well Site Size: 2" Material: Poly
 Variance: Age: Contents: Crude Oil

Integrity Summary

Failures: Spills: Repairs Made:
 Coatings: H2S: Cathodic Protection:

Pressure Testing

Witnessed: Test Result: Charted:

COGCC Rules (check all that apply)

☐ 1101. Installation and Reclamation ☐ 1102. Operations, Maintenance, and Repair ☐ 1103. Abandonment

Comment: Flowline abandonment completed on (2) 2" HDPE (Poly) flowlines; (1) 2" Natural gas flowline and (1) 2" Crude Oil flowline. The flowlines were purged of hydrocarbons (flushed using fresh water) prior to this field inspection. The risers have been removed; both flowlines have been cut and sealed (capped via poly fusion welding) at both ends and approximately 3'-4' below grade. The flowlines originate and terminate at the same points; at (PA) well site @ 40.631797/-105.041103 and west side intersection of Morningstar Way and Brightwater Dr @ 40.37854/-105.02921

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
**Note: Notice of abandonment must be filed with the Commission and with the local governmental designee or local government jurisdiction via COGCC form 42.	maclarej	06/27/2017
Note: There are active flowlines that were observed in the same excavation (near intersection Morningstar Way/ Brightwater Drive) as the abandoned flowline endpoints.	maclarej	06/27/2017

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
674603417	MSSU 30-4 Flowlines abandoned at well site	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4182121
674603418	MSSU Flowlines abandoned near road intersection	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4182122