

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/20/2017

Submitted Date:

06/21/2017

Document Number:

687400062

**FIELD INSPECTION FORM**

Loc ID 319872 Inspector Name: Kraich, Adam On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10454  
Name of Operator: PETROSHARE CORPORATION  
Address: 9635 MAROON CIRCLE #400  
City: ENGLEWOOD State: CO Zip: 80112

**Findings:**

13 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Powell, Harold	(918)-774-3120	hpowell@petrosharecorp.com	Field Op Manager
Lloyd, Bill		blloyd@petrosharecorp.com	Operations Manager
Witsell, Fred	303-500-1168	fwitsell@petrosharecorp.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
201671	WELL	PR	12/31/2007	GW	001-07074	L.W. MOORE GAS UNIT 1	PR

**General Comment:**

Empty text area for general comments.

**Location**

Overall Good:

**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:			Date:
Type	BATTERY		
Comment:	Adequate		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:			Date:

Emergency Contact Number:

Comment: Adequate

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	TANK BATTERY		
Comment:	4 strad barbed wire		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Rod iron		
Corrective Action:			Date:
Type	SEPARATOR		
Comment:	Square tubing		
Corrective Action:			Date:

**Equipment:**

Type: Gas Meter Run	# 1		corrective date
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		

Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:	Separator exhaust		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Shares berms with produced water tank			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLs	PBV FIBERGLASS		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Shares berms with production tank			
Corrective Action:				Date:

**Venting:**

Yes/No		
Comment:		
Corrective Action:		
		Date:

**Flaring:**

Type	
------	--

Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 201671 Type: WELL API Number: 001-07074 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401314388	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4176184">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4176184</a>
687400063	Inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4176178">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4176178</a>