

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/20/2017

Submitted Date:

06/21/2017

Document Number:

687400064**FIELD INSPECTION FORM**

Loc ID 335737 Inspector Name: Kraich, Adam On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 90615Name of Operator: TUDEX PETROLEUM INCAddress: UNIT E 2121 39TH AVENUE NECity: CALGARY State: AB Zip: T2E 6R7**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**10 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Conn, Lionel	1 40 3250 7225	tudorcorp@hotmail.ca	President
Leonard, Mike		mike.leonard@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
203258	WELL	PR	08/01/2014	OW	001-08767	HI-LAND 10-B	PR
203259	WELL	PR	05/01/2015	OW	001-08768	HI-LAND 10-G	PR

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment: No emergency contact info at wellhead.

Corrective Action: Install sign to comply with Rule 210.b.

Date: 07/21/2017

Good Housekeeping:

Type TRASH

Comment: Trash stored inside and outside of separator housing, and barrel at wellhead. See photos.

Corrective Action: Comply with Rule 603.f using the Rule 603.f guidance document for further details.

Date: 07/03/2017

Type OTHER

Comment: Stained soil in separator cabinet, see photos

Corrective Action:

Date:

Overall Good: ☐**Spills:**

Type Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type PUMP JACK

Comment: Chainlink around wellheads and pumping units.

Corrective Action:

Date:

Equipment:

corrective date

Type: Bird Protectors

#

Comment: LOCATED ON SEPARATOR EXHAUST

Corrective Action:

Date:

Type: Gas Meter Run

1

Comment:

Corrective Action:

Date:

Type: Prime Mover

1

Comment: Natural gas fired engine

Corrective Action:

Date:

Type: Pump Jack

1

Comment: Conventional

Corrective Action:

Date:

Type: Horizontal Heated Separator

1

Comment:

Corrective Action:

Date:

Type: Other	# 1	
Comment:	Circulation pump located in separator housing shed.	
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected FacilitiesFacility ID: 203258 Type: WELL API Number: 001-08767 Status: PR Insp. Status: PR**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____Comment: Corrective Action: Date: _____Facility ID: 203259 Type: WELL API Number: 001-08768 Status: PR Insp. Status: PR**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____Comment: No production records submitted since January 2016. Well must have a successful mechanical integrity test performed or plugged as directed by Rule 319 b (3)Corrective Action: Contact dnr_cogccengineering@state.co.us with resolution plan. Date: 07/11/2017**COGCC Comments**

Comment	User	Date
	kraicha	06/21/2017

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401314389	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4176185
687400068	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4176179