

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/15/2017

Submitted Date:

06/20/2017

Document Number:

687900044**FIELD INSPECTION FORM**

Loc ID 334225 Inspector Name: DURAN, JOHN On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10084Name of Operator: PIONEER NATURAL RESOURCES USA INCAddress: 5205 N O'CONNOR BLVD STE 200City: IRVING State: TX Zip: 75039**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
Distribution, Pioneer	972-444-9001	COGCC.Inspections@pxd.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
258602	WELL	PR	02/12/2004	GW	071-07108	MUSTANG 41-30	PR

General Comment:

2017 Flowline NTO Inspection
Shadowing Operator Pressure Testing Team
Pioneer Team : Zeke Sanchez, Vince Santisteven, Vince Santisteven Jr. and John Gonzales.

LocationOverall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date: _____
Corrective Action:		

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Flow Line	# 1		corrective date
Comment:	IN USE : 1 - 2" Fuel/Gas carbon steel riser at separator (37.23535/-104.81295).		
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 258602 Type: WELL API Number: 071-07108 Status: PR Insp. Status: PR**Completion**

Operation:

Date Flowback:

Contractor:

Comment:

Corrective Action:

Date:

Flowline

#1 Type: Well Site

1 of Lines

Flowline DescriptionFlowline Type: Well SiteSize: 2"Material: Carbon SteelVariance: NoAge: 15-20 YrsContents: Natural GasIntegrity Summary

Failures:

Spills: NoRepairs Made: NoCoatings: Yes ExternalH2S: NoCathodic Protection: NoPressure TestingWitnessed: YesTest Result: PassCharted: YesCOGCC Rules(check all that apply)☐ 1101. Installation and Reclamation☒ 1102. Operations, Maintenance, and Repair☐ 1103. Abandonment

Comment:

No physical chart in the field, but Pioneer used a Manifold Pressure Transducer : GP : 50, Model #311ZCPZ2FNDR4, Serial #183317, Pressure Range : 0 - 100 psig, (Records pressure in the field). Manifold also has liquid guage : 0 - 100 psig. Time : 11:26 am, P=27 psig, Time : 11:41 am, P=28 psig.

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401313830	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4175774