

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/26/2017

Submitted Date:

06/28/2017

Document Number:

666803306**FIELD INSPECTION FORM**

Loc ID 335119 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10531Name of Operator: VANGUARD OPERATING LLCAddress: 5847 SAN FELIPE #3000City: HOUSTON State: TX Zip: 77057**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:18 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email | Comment |
|----------------|--------------|--------------------|--|
| Axelson, Aaron | 970-230-0926 | aaxelson@vnrlc.com | Sr. Production Foreman |
| Ghan, Scott | | sghan@vnrlc.com | Sr. EH&S |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------------|-------------|
| 277335 | WELL | PR | 11/24/2005 | GW | 045-10678 | ANCHONDO 42B-20-692 | PR |
| 277336 | WELL | PR | 11/04/2005 | GW | 045-10679 | ANCHONDO 42D-20-692 | PR |
| 277337 | WELL | PR | 12/29/2005 | GW | 045-10680 | ANCHONDO 32D-20-692 | PR |
| 277338 | WELL | PR | 10/28/2005 | GW | 045-10681 | ANCHONDO 32B-20-692 | PR |
| 290416 | WELL | PR | 05/03/2012 | GW | 045-14104 | ANCHONDO 32A-20-692 | PR |
| 290417 | WELL | PR | 04/17/2012 | GW | 045-14103 | ANCHONDO 32C-20-692 | PR |
| 290418 | WELL | PR | 10/09/2007 | GW | 045-14102 | ANCHONDO 42A-20-692 | PR |
| 290419 | WELL | PR | 10/03/2007 | GW | 045-14101 | ANCHONDO 42C-20-692 | PR |

General Comment:[2017 Flowline NTO Inspection 1000' Buffer](#)

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

| Type | Area | Volume |
|------|------|--------|
| | | |

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Flow Line

#

Comment: Not in use 2-2", see photo

Corrective Action:

Date:

Type: Plunger Lift

4

Comment: 39.514561/-107.685285

Corrective Action:

Date:

Type: Horizontal Heated Separator

8

Comment: 39.514799/-107.685460

Corrective Action:

Date:

Type: Plunger Lift

4

Comment: 39.514204/-107.685160

Corrective Action:

Date:

Type: Flow Line

#

Comment: In use; 8-2" steel risers at wellhead, 24-2", 4-3", 3-1" risers at separators, 3-3", 4-1", 1-2" risers at tanks, 1-1" gas feed to ECB

Corrective Action:

Date:

Type: Gas Meter Run

0

Comment:

Corrective Action:

Date:

Type: Emission Control Device

1

Comment: 39.514812/-107.685332

Corrective Action:

Date:

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|-----------------------|
| CONDENSATE | 4 | 300 BBLS | STEEL AST | | 39.514788,-107.685214 |
| Comment: | | | | | |
| Corrective Action: | | | | | |
| Date: | | | | | |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| | | | | | |
|--------------------|----------|---------------------|---------------------|-------------|-------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
| Earth | Adequate | Walls Sufficient | Base Sufficient | Adequate | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Venting:

| | | | |
|--------------------|-----------------------|-------|--|
| Yes/No | YES | | |
| Comment: | Bradenhead valve open | | |
| Corrective Action: | | Date: | |

Flaring:

| | | | |
|--------------------|--|-------|--|
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| Inspected Facilities | | | | | | | | | |
|-----------------------|--------------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 277335 | Type: | WELL | API Number: | 045-10678 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Plunger lift | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 277336 | Type: | WELL | API Number: | 045-10679 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Plunger lift | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 277337 | Type: | WELL | API Number: | 045-10680 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Plunger lift | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 277338 | Type: | WELL | API Number: | 045-10681 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Plunger lift | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 290416 | Type: | WELL | API Number: | 045-14104 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Plunger lift | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 290417 | Type: | WELL | API Number: | 045-14103 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Plunger lift | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 290418 | Type: | WELL | API Number: | 045-14102 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Plunger lift | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 290419 | Type: | WELL | API Number: | 045-14101 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Plunger lift | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |

| |
|--|
| |
|--|

Environmental

Spill/Remediation:

Comment:

Corrective
Action:

Date:

Emission Control Burner (ECB): YES

Comment:

Pilot: ON

Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | Gravel | Pass | | | |
| Slope Roughening | Pass | | | | | |
| | | Ditches | Pass | | | |
| | | Culverts | Pass | | | |
| Gravel | Pass | | | | | |

Comment:

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------|---|
| 666803311 | NT0 3 | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4183165 |
| 666803312 | NT0 2 | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4183166 |
| 666803313 | NT0 | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4183167 |