

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/26/2017

Submitted Date:

06/28/2017

Document Number:

666803307**FIELD INSPECTION FORM**

Loc ID 335083	Inspector Name: Murray, Richard	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input checked="" type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 16 Number of Comments 0 Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested
Operator Information: OGCC Operator Number: <u>10531</u> Name of Operator: <u>VANGUARD OPERATING LLC</u> Address: <u>5847 SAN FELIPE #3000</u> City: <u>HOUSTON</u> State: <u>TX</u> Zip: <u>77057</u>				

Contact Information:

Contact Name	Phone	Email	Comment
Ghan, Scott		sghan@vnrlc.com	Sr. EH&S
Axelsson, Aaron	970-230-0926	aaxelson@vnrlc.com	Sr. Production Foreman

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
277912	WELL	PR	11/01/2014	GW	045-10809	GUCCINI 41D-20-692	PR
277913	WELL	PR	06/07/2006	GW	045-10810	GUCCINI 41B-20-692	PR
277914	WELL	PR	06/07/2006	GW	045-10811	GUCCINI 31D-20-692	PR
277915	WELL	PR	06/05/2006	GW	045-10812	GUCCINI 31B-20-692	PR
290198	WELL	PR	04/17/2012	GW	045-14053	GUCCINI 31A-20-692	PR
290200	WELL	PR	04/17/2012	GW	045-14052	GUCCINI 41C-20-692	PR
290202	WELL	PR	09/05/2007	GW	045-14051	GUCCINI 31C-20-692	PR
290203	WELL	PR	09/05/2007	GW	045-14050	GUCCINI 41A-20-692	PR

General Comment:

2017 Flowline NTO Inspection 1000' Buffer
 Shared tank battery with facilities #418614

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Ancillary equipment

3

Comment: [Chemical unit at wellhead](#)

Corrective Action:

Date:

Type: Plunger Lift

8

Comment: [39.517196/-107.687442](#)

Corrective Action:

Date:

Type: Flow Line

#

Comment: [In use; 8-2" steel risers at wellhead, 8-2", 16-3", 2-4" risers at separators](#)

Corrective Action:

Date:

Type: Horizontal Heated Separator

8

Comment: [39.517008/-107.688522](#)

Corrective Action:

Date:

Venting:

Yes/No YES

Comment: [Bradenhead valves open](#)

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities									
Facility ID:	277912	Type:	WELL	API Number:	045-10809	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	277913	Type:	WELL	API Number:	045-10810	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	277914	Type:	WELL	API Number:	045-10811	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	277915	Type:	WELL	API Number:	045-10812	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	290198	Type:	WELL	API Number:	045-14053	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	290200	Type:	WELL	API Number:	045-14052	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	290202	Type:	WELL	API Number:	045-14051	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	290203	Type:	WELL	API Number:	045-14050	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			

--

Environmental	
Spill/Remediation:	
Comment:	
Corrective Action:	Date:
Emission Control Burner (ECB): NO	
Comment:	
Pilot:	Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel	Pass			
		Ditches	Pass			
		Rip Rap	Pass			
		Check Dams	Pass			
Ditches	Pass					
Rip Rap	Pass					
		Culverts	Pass			
Gravel	Pass					
Berms	Pass					

Comment:

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
666803314	NTO 2	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4183259
666803315	NTO	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4183260