

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/22/2017

Submitted Date:

06/28/2017

Document Number:

674901775**FIELD INSPECTION FORM**

Loc ID 325308 Inspector Name: Hughes, Jim On-Site Inspection ☐ 2A Doc Num:

Operator Information:OGCC Operator Number: 10254Name of Operator: RED MESA HOLDINGS/O&G LLCAddress: 5619 DTC PARKWAY - STE 800City: GREENWOOD State: CO Zip: 80111**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
☒ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
Adamczyk, Megan		megan.adamczyk@state.co.us	
Fischer, Alex		alex.fischer@state.co.us	
Andrews, Dave		david.andrews@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214536	WELL	PR	08/01/2013	GW	067-06139	CUSHING C-1	EI

General Comment:

On June 22, 2017 COGCC SW EPS Jim Hughes conducted a follow up environmental field inspection of the Red Mesa Holdings Cushing #C-1. For the most recent field inspection report for this facility, please refer to document #674901767. The landowners where present during this field inspection to discuss complaint #200443077.

Location**Lease Road:**

Type	Access		
comment:	Locked gate on access road.		
Corrective Action	L	Date:	

Overall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:	Sign propped up against well head.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date: _____
Corrective Action:		

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	214536	Type:	WELL	API Number:	067-06139	Status:	PR	Insp. Status:	EI

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
On June 22, 2017 COGCC SW EPS Jim Hughes conducted a follow up environmental field inspection of the Red Mesa Holdings Cushing #C-1. For the most recent field inspection report for this facility, please refer to document #674901767. The landowners were present during this field inspection to discuss complaint #200443077. The purpose of this site visit was to inspect the valve and plug installed on what is believed to be the bradenhead access. This 2" nipple was the cause of concern in complaint #200443077. The landowners were satisfied with the actions taken on 6/21/17. The plugging of the bradenhead access was discussed with the COGCC SW Regional Engineer.	hughesj	06/28/2017

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
674901776	Cushing C-1 well head w/ plug and valve on bradenhead.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4184294
674901777	Bull plug and valve installed on bradenhead.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4184295