

**FORM
INSP**Rev
X/15**State of Colorado****Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/26/2017

Submitted Date:

06/28/2017

Document Number:

675103691**FIELD INSPECTION FORM**
 Loc ID 316316 Inspector Name: GRANAHAH, KYLE On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 10200Name of Operator: PETROHUNTER OPERATING COMPANYAddress: 910 SIXTEENTH STREET SUITE 208City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
263059	WELL	TA	02/09/2009	GW	103-10230	BMU 2520	EG

General Comment:

On location to perform 2017 flowline compliance and ensure well is TA - all openings bullplugged/needle valved. 1 - 2" steel flow line with 1 riser - Riser A capped/painted orange/ LOTO; Not able to find riser B at time of work - notified engineering.

Inspected Facilities									
Facility ID:	263059	Type:	WELL	API Number:	103-10230	Status:	TA	Insp. Status:	EG
Idle Well									
Purpose:		<input type="checkbox"/> Shut In		<input checked="" type="checkbox"/> Temporarily Abandoned		Reminder: EQUIPMENT PRESENT/DISCONNECTED			
Comment:		<div>On location to perform 2017 flowline compliance and ensure well is TA - all openings bulplugged/needle valved. 1 - 2" steel flow line with 1 riser - Riser A capped/painted orange/ LOTO; Not able to find riser B at time of work - notified engineering.</div>							
Corrective Action:							Date:		