

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/26/2017

Submitted Date:

06/28/2017

Document Number:

675103692**FIELD INSPECTION FORM**
 Loc ID 316200 Inspector Name: GRANAHAH, KYLE On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_
**Operator Information:**OGCC Operator Number: 10200Name of Operator: PETROHUNTER OPERATING COMPANYAddress: 910 SIXTEENTH STREET SUITE 208City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
256445	WELL	TA	06/04/2004	GW	103-09995	BUCKSKIN MESA UNIT 2571	EG

**General Comment:**

On location to perform 2017 flowline compliance and ensure well is TA - all openings bullplugged/needle valved. 1 - 2" steel flow line with 2 risers - Riser A capped/painted orange/ LOTO; Riser B capped/painted orange/LOTO

Inspected Facilities										
Facility ID:	256445	Type:	WELL	API Number:	103-09995	Status:	TA	Insp. Status:	EG	
Idle Well										
Purpose:		<input type="checkbox"/> Shut In		<input checked="" type="checkbox"/> Temporarily Abandoned		Reminder:				EQUIPMENT PRESENT/DISCONNECTED
Comment:		<div>On location to perform 2017 flowline compliance and ensure well is TA - all openings bulplugged/needle valved. 1 - 2" steel flow line with 2 risers - Riser A capped/painted orange/ LOTO; Riser B capped/painted orange/LOTO</div>								
Corrective Action:		<div></div>						Date:		