

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/28/2017

Submitted Date:

06/28/2017

Document Number:

673404737**FIELD INSPECTION FORM**

Loc ID 399362 Inspector Name: Waldron, Emily On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 45830Name of Operator: K-N OPERATING CORPAddress: P O BOX 162050City: AUSTIN State: TX Zip: 78716-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	
Floyd, James		jfloyd@acexploration.com	
Andrews, Dave		david.andrews@state.co.us	
Burger, Craig		craig.burger@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
232701	WELL	DA	10/28/1983	DA	107-06115	PAGODA 1-31	DA

General Comment:

Inspector on location to witness removal of above ground dry hole marker and replacement with below grade marker plate.

Inspected FacilitiesFacility ID: 232701 Type: WELL API Number: 107-06115 Status: DA Insp. Status: DA**COGCC Comments**

Comment	User	Date
Above ground dry hole marker was excavated to 3 feet below grade. Dry hole marker was cut off at surface casing and new marker plate was welded on. Excavation was backfilled and above ground marker and debris were removed from location.	waldrone	06/28/2017

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
673404738	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4184630