



**Inspected Facilities**

Facility ID: 270114 Type: WELL API Number: 103-10391 Status: SI Insp. Status: EG

**Flowline**

#1	Type: Well Site	of Lines
----	-----------------	----------

Flowline Description

Flowline Type: Well Site Size: 4" Material: Carbon Steel  
 Variance: No Age: Contents:

Integrity Summary

Failures: Spills: Repairs Made:  
 Coatings: H2S: Cathodic Protection:

Pressure Testing

Witnessed: Yes Test Result: Charted: Yes

COGCC Rules(check all that apply)

1101. Installation and Reclamation  1102. Operations, Maintenance, and Repair  1103. Abandonment

Comment: Isolated line at wellhead 39.82246, -108.24179 and where gauge was placed at 39.82246, -108.24179. Line at 113 psi at arrival, pressured up to 292.8 psi. At 5 minutes 293.1 psi, at 10 minutes 293.2 psi, at 15 minutes 293.3 psi.

Corrective Action:

Date:

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
673404754	Pressure test photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4186549">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4186549</a>