

FORM
INSPRev
X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/22/2017

Submitted Date:

06/23/2017

Document Number:

681700580

FIELD INSPECTION FORM

Loc ID 320663 Inspector Name: Arauza, Steven On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 74165
 Name of Operator: RENEGADE OIL & GAS COMPANY LLC
 Address: 6155 S MAIN STREET #210
 City: AURORA State: CO Zip: 80016

Findings:

17 Number of Comments
6 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Ingvie, Ed	(303) 680-4725	ed@renegadeoilandgas.com	All Inspections
Leonard, Mike		mike.leonard@state.co.us	
		dnr_cogccengineering@state.co.us	
Condill, J.B.	(303) 680-4725	jbrog@aol.com	All Inspections
Espinosa, Bill	(303) 829-4982	billespinosa30@yahoo.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
204346	WELL	PR	09/08/1997	OW	005-06431	PAR-STATE 28-1	EI

General Comment:

[COGCC Environmental Inspection.](#)

Location

Overall Good:

Signs/Marker:

Type	BATTERY		
Comment:	No sign for Parr State 28-14 #2 at battery.		
Corrective Action:	If Parr State 28-14 #2 is producing to this battery, install sign to comply with Rule 210.b.	Date:	08/23/2017
Type	TANK LABELS/PLACARDS		
Comment:	Adequate.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Adequate.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	TANK BATTERY		
Comment:	Barbed wire fence.		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Barbed wire fence.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Barbed wire fence.		
Corrective Action:		Date:	

Equipment:

Type: Bird Protectors	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Other	# 2		
Comment:	Valves on either side of wellhead are exposed to the atmosphere.		
Corrective Action:	Cap or install bull plugs on exposed valves to prevent spills. Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.	Date:	07/23/2017

Type: Pump Jack	# 1	
Comment:	Localized, oil-stained soil at wellhead, prime mover, and pump jack exhaust (see photos).	
Corrective Action:	Remove and properly dispose of oily waste and stained soil.	Date: 07/23/2017
Type: Horizontal Heated Separator	# 1	
Comment:	Valve on south side of separator is exposed to atmosphere (see photos)	
Corrective Action:	Install bull plug on exposed valve to prevent spills. Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.	Date: 07/23/2017
Type: Deadman # & Marked	# 4	
Comment:		
Corrective Action:		Date:
Type: Gas Meter Run	# 1	
Comment:		
Corrective Action:		Date:
Type: Flow Line	# 2	
Comment:	NOT IN USE: Capped 1" steel riser and uncapped 2" steel riser on west side of meter run (see photos).	
Corrective Action:	Contact the Engineering Integrity section to discuss flowline abandonment requirements per Rule 1103. Along with the rule, the COGCC Operator Guidance, Rules 1101, 1102, and 1103: Flowline Guidance 1101 and 1102 guidance document can provide further details. Contact dnr_cogccengineering@state.co.us with resolution plan.	Date: 07/05/2017

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLs	FIBERGLASS AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient		Adequate
Comment:	Earthen berms shared with crude oil ASTs.			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	3	300 BBLs	STEEL AST		,
Comment:	Localized, oil-stained soil on south side of northeast crude oil AST (see photos). Various tank valves are exposed to the atmosphere.				
Corrective Action:	Remove and properly dispose of oily waste. Install bull plugs on exposed valves to prevent spills. Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.				Date: 07/23/2017

Paint				
Condition	Adequate			
Other (Content)				
Other (Capacity)				
Other (Type)				
Berms				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent		Adequate
Comment:	Earthen berms shared with produced water AST.			
Corrective Action:				Date:
Venting:				
Yes/No				
Comment:				
Corrective Action:				Date:
Flaring:				
Type				
Comment:				
Corrective Action:				Date:

Inspected FacilitiesFacility ID: 204346 Type: WELL API Number: 005-06431 Status: PR Insp. Status: EI**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401317717	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4179448
681700590	Battery sign.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4179431
681700591	Exposed valve on crude oil tank (1)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4179432
681700592	Exposed valve on crude oil tank (2)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4179433
681700593	Stained soil and exposed valves south of NE CO AST	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4179434
681700594	Exposed valve on south end of separator.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4179435
681700595	Flowline risers west of meter run.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4179436
681700596	Well sign and stained soil at muffler.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4179437
681700597	Oil-stained soil under prime mover & day tank	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4179438
681700598	Oil-stained soil and exposed valves at wellhead (1)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4179439
681700599	Oil-stained soil and exposed valves at wellhead (2)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4179440