

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/22/2017

Submitted Date:

06/23/2017

Document Number:

681700581

FIELD INSPECTION FORM

Loc ID 413721 Inspector Name: Arauza, Steven On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 74165
Name of Operator: RENEGADE OIL & GAS COMPANY LLC
Address: 6155 S MAIN STREET #210
City: AURORA State: CO Zip: 80016

Findings:

- 9 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Ingvie, Ed	(303) 680-4725	ed@renegadeoilandgas.com	All Inspections
Condill, J.B.	(303) 680-4725	jbcrog@aol.com	All Inspections
Espinosa, Bill	(303) 829-4982	billespinosa30@yahoo.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
412570	WELL	PR	05/31/2012	OW	005-07144	Par State 28-14 #2	EI

General Comment:

[COGCC Environmental Inspection.](#)

Empty area for additional comments or notes.

Location			
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Adequate.		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:			Date:
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
Crude Oil	WELLHEAD	<= 1 bbl	
Comment:	Localized, oil-stained soil at wellhead.		
Corrective Action:	Remove and properly dispose of oily waste. Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.		Date: <u>07/23/2017</u>
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	PUMP JACK		
Comment:	Barbed wire fence.		
Corrective Action:			Date:
Equipment:			
Type: Prime Mover			corrective date
	# 1		
Comment:	Localized, stained soil beneath prime mover.		
Corrective Action:	Remove and properly dispose of oily waste. Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.		Date: <u>07/23/2017</u>
Type: Other			#
Comment:	1" valve at wellhead is exposed to atmosphere.		
Corrective Action:	Cap valve to prevent leaks. Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.		Date: <u>07/23/2017</u>
Venting:			
Yes/No			
Comment:			
Corrective Action:			Date:
Flaring:			
Type			
Comment:			

Corrective Action:

Date:

Inspected FacilitiesFacility ID: 412570 Type: WELL API Number: 005-07144 Status: PR Insp. Status: EI**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401317719	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4179449
681700600	Well sign.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4179441
681700601	Stained soil and exposed valve at wellhead.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4179442
681700602	Stained soil beneath prime mover.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4179443