

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/29/2017

Submitted Date:

06/30/2017

Document Number:

673715672**FIELD INSPECTION FORM**

Loc ID 320749 Inspector Name: Sherman, Susan On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 19035Name of Operator: OVERLAND RESOURCES LLCAddress: SUITE C18 PMB 440City: GREENWOOD State: CO Zip: 80121**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:8 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Pandolfo, Chris	(650) 387-6506	cpandolfo@gmail.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
204782	WELL	PR	12/20/2015	OW	005-06867	LINNEBUR 1-20	EG

General Comment:2017 Flowline NTO Inspection 1000' Buffer

LocationOverall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 970-395-7641

Corrective Action:

Date: _____

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Flow Line	# 3		
Comment:	NOT IN USE: 2-2" steel risers and valves east of treater shed (see attached photo), GPS 39.59380, -104.34304; 1-1" steel riser at back of pumping unit, GPS 39.59523, -104.34478. Paint flouresant orange, LOTO and schedule abandonment per Rule 1103.		
Corrective Action:		Date:	

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 204782 Type: WELL API Number: 005-06867 Status: PR Insp. Status: EG

Producing Well

Comment: PR. Apr 2017 reported to COGCC database.

Corrective Action:

Date:

Flowline

#1 Type: Well Site

of Lines

Flowline Description

Flowline Type: Well Site

Size: 2"

Material: Carbon Steel

Variance:

Age:

Contents:

Integrity Summary

Failures:

Spills:

Repairs Made:

Coatings:

H2S:

Cathodic Protection:

Pressure Testing

Witnessed: Yes

Test Result: Pass

Charted: No

COGCC Rules(check all that apply)

☐ 1101. Installation and Reclamation☒ 1102. Operations, Maintenance, and Repair☐ 1103. Abandonment

Comment: Flowline test from well to treater. 0 psi prior to test.

0 min 15 psi
 5 min 15 psi
 10 min 15 psi
 15 min 15 psi
 0 psi after test
 GPS 39.59519, -104.34470

Corrective Action:

Date:

#2 Type: Sales Line

of Lines

Flowline Description

Flowline Type: Sales Line

Size: 2"

Material: Carbon Steel

Variance:

Age:

Contents:

Integrity Summary

Failures:

Spills:

Repairs Made:

Coatings:

H2S:

Cathodic Protection:

Pressure Testing

Witnessed: Yes

Test Result: Pass

Charted: No

COGCC Rules(check all that apply)

☐ 1101. Installation and Reclamation☒ 1102. Operations, Maintenance, and Repair☐ 1103. Abandonment

Comment: Flowline test from treater to GMR. 0 psi prior to test.

0 min 45 psi
 5 min 42 psi
 10 min 41 psi
 15 min 40 psi
 0 psi after test
 GPS 39.59373, -104.34312

Corrective Action:

Date:

#3	Type: Dump Line	of Lines	
----	-----------------	----------	--

Flowline Description

Flowline Type: <u>Dump Line</u>	Size: <u>2"</u>	Material: <u>Carbon Steel</u>
Variance:	Age:	Contents:

Integrity Summary

Failures:	Spills:	Repairs Made:
Coatings:	H2S:	Cathodic Protection:

Pressure Testing

Witnessed: <u>Yes</u>	Test Result: <u>Pass</u>	Charted: <u>No</u>
-----------------------	--------------------------	--------------------

COGCC Rules(check all that apply)

☐ 1101. Installation and Reclamation ☒ 1102. Operations, Maintenance, and Repair ☐ 1103. Abandonment

<u>Comment:</u>	<div>Flowline test from treater to hot oil line. 0 psi prior to test. 0 min 40 psi 5 min 40 psi 10 min 40 psi 15 min 40 psi 0 psi after test GPS 39.59380, -104.34341</div>
Corrective Action:	
	Date:

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: house is ~400' NW of well and a house is 400' SW of tank battery**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND
SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

- 1003b. Area no longer in use? _____ Production areas stabilized ? _____
- 1003c. Compacted areas have been cross ripped? _____
- 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
- Cuttings management: _____
- 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
- Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment _____

Corrective Action _____ Date _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads _____ Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location ☐ Multi-Well Location ☐

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
673715681	Overland Linnebur 1-20 EI	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4186808