

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/28/2017

Submitted Date:

06/30/2017

Document Number:

674901782**FIELD INSPECTION FORM**

Loc ID 334249 Inspector Name: Hughes, Jim On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10000Name of Operator: BP AMERICA PRODUCTION COMPANYAddress: 380 AIRPORT RDCity: DURANGO State: CO Zip: 81303**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**14 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Beebe, Sabre	970-375-7530	Sabre.Beebe@bp.com	SW Inspection Reports
Leonard, Mike		mike.leonard@state.co.us	
Fischer, Alex		alex.fischer@state.co.us	
Inspections, All		SanJuanCOGCC@bp.com	SW Inspection Reports

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
89110	WELL	PR	12/31/2001	GW	067-08214	BEAVER CREEK B 2	EI

General Comment:

On June 28, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the BP Beaver Creek B #2. For the most recent field inspection report of this facility, please refer to document #680400927.

Location			
Lease Road:			
Type	Access		
comment:			
Corrective Action	L		Date:
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Partially buried vessel on location is not in compliance with Rule 210.d.		
Corrective Action:	Install sign to comply with Rule 210.d.		Date: 08/30/2017
Type	WELLHEAD		
Comment:	Sign mounted to metal building housing Bayfield #1 well head.		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Free standing sign near location entrance for Beaver Creek B #2.		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	Operator emergency contact information posted on location sign near entrance.		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	TRASH		
Comment:	Unlabeled, empty 5 gal. container in Bayfield #1 well house.		
Corrective Action:	Comply with Rule 603.f using the Rule 603.f guidance document for further details.		Date: 07/10/2017
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No _____			
Comment: _____			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	Stock panel fencing.		
Corrective Action:			Date:
Type	SEPARATOR		
Comment:	Stock panel fencing around all equipment on location.		
Corrective Action:			Date:
Equipment:			
Type: Other	# 1		corrective date
Comment:	Metal building housing Bayfield #1 well head.		

Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Telemetry.		
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	PBV STEEL		37.216763,-107.566119
Comment:	Tank label and placard are peeling off of tank. Paint is peeling off of tank. Capacity is not labeled.				
Corrective Action:	Install sign to comply with Rule 210.d.				Date: 09/01/2017

Paint

Condition	Inadequate
Other (Content)	
Other (Capacity)	Unknown
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches	Pass					
Berms	Pass	Compaction	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>On June 28, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the BP Beaver Creek B #2. For the most recent field inspection report of this facility, please refer to document #680400927.</p> <p>During this field inspection, an empty, unlabeled 5 gallon container with brown staining inside was observed within the well house for the Bayfield #1 injection well.</p> <p>The partially buried vessel in the southwest corner of the location does not comply with Rule 210.d. The label and placard are peeling off and there is no capacity labelled. The paint on this tank is also peeling off.</p>	hughesj	06/30/2017

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
674901783	Beaver Creek B #2 location photo.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4187106
674901784	PBV does not comply with Rule 210.d.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4187107
674901785	Labels and paint are peeling off of PBV.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4187108
674901786	Unlabeled container in Bayfield #1 well house.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4187109