

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/17/2017

Submitted Date:

06/28/2017

Document Number:

680101954**FIELD INSPECTION FORM**Loc ID 399062 Inspector Name: Colby, Lou On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 8220Name of Operator: BIASI\* BRUNOAddress: P O BOX 60City: BUNKERVILLE State: NV Zip: 89007**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Thompson, Bud		BLThomps@BLM.gov	
Colby, Lou		lou.colby@state.co.us	
Williamson, Craig	970-878-3800	cwilliamson@blm.gov	Petroleum Engineer

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
261676	WELL	PA	07/01/1988	OW	103-40370	WOOSLEY 2	RI

**General Comment:**

2017 Flowline NTO Inspection 1000' Buffer. There is No visual evidence of equipment (Flowline or Risers) on location. No indication of other facilities identified with aerial imagery assessment.

This Location has received three Action Required Inspections. Equipment, assorted piping, Debris, & Tanks leaking Crude are still on Location. Reclamation Inspection for Location will be submitted seperately from this NTO Inspection.

**Inspected Facilities**Facility ID: 261676 Type: WELL API Number: 103-40370 Status: PA Insp. Status: RI**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
680101985	Inspection Photo	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4187110">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4187110</a>