

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/21/2017

Submitted Date:

06/27/2017

Document Number:

674603410

FIELD INSPECTION FORM

Loc ID 333405 Inspector Name: Maclaren, Joe On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10084
Name of Operator: PIONEER NATURAL RESOURCES USA INC
Address: 5205 N O'CONNOR BLVD STE 200
City: IRVING State: TX Zip: 75039

Findings:

- 2 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
Distribution, Pioneer	972-444-9001	COGCC.Inspections@pxd.com	
ROYBAL, JAMES	719-845-4323	james.roybal@pxd.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
289796	WELL	TA	07/28/2015	GW	071-09224	MORNEAU 44-32	EG
294686	WELL	PR	04/23/2008	GW	071-09501	MORNEAU 44-32TR	EG

General Comment:

[2017 Flowline NTO Inspection 1000' Buffer; Shadowing Operator Identifying/ Integrity Team using RMLD and FLIR Equipment](#)

Inspected Facilities

Facility ID: 289796 Type: WELL API Number: 071-09224 Status: TA Insp. Status: EG

Facility ID: 294686 Type: WELL API Number: 071-09501 Status: PR Insp. Status: EG

Flowline

#1	Type:	of Lines
----	-------	----------

Flowline Description

Flowline Type: _____ Size: _____ Material: _____
 Variance: _____ Age: _____ Contents: _____

Integrity Summary

Failures: _____ Spills: _____ Repairs Made: _____
 Coatings: _____ H2S: _____ Cathodic Protection: _____

Pressure Testing

Witnessed: _____ Test Result: _____ Charted: _____

COGCC Rules(check all that apply)

1101. Installation and Reclamation 1102. Operations, Maintenance, and Repair 1103. Abandonment

Comment: COGCC Inspector met with Pioneer Resources Operations Compliance Foreman Zachary Snow (along with other personnel) and witnessed Remote Methane Leak Detection (RMLD) instrumentation being used at this location. The flowlines and production equipment on site were surveyed for gas leaks; NO leaks were detected with the RMLD (or FLIR camera). Note: There are (2) flowlines/ w end point risers associated with the Morneau 44-32 (TA/ API 071-09224) marked with fluorescent paint (per NTO) scheduled for removal and abandonment.

Corrective Action: _____

Date: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401320354	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4181587