

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/15/2017

Submitted Date:

06/27/2017

Document Number:

674603413**FIELD INSPECTION FORM**Loc ID 307108 Inspector Name: Maclaren, Joe On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10312Name of Operator: PROSPECT ENERGY LLCAddress: 1036 COUNTRY CLUB ESTATES DRCity: CASTLE ROCK State: CO Zip: 80108**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Giltner, Ward		wgiltner@yahoo.com	
Twele, Megan		mtwele@progressivepcs.net	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
Gracey, Cameron		graceyservices@msn.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
216884	WELL	PR	03/30/1994	OW	069-06071	MUDDY SANDSTONE UNIT 30-1	EG

General Comment:

COGCC Engineering Integrity Inspector met with Prospect Energy Field Manager Cam Gracey and performed a flowline (abandonment) field inspection. The MSSU 30-1 (API 069-06071) has been plugged and abandoned (Form 6 Intent Doc #401252494 received on 04/06/17). Details of the observations made during this field inspection are available in the flowline section of this report. Photo's uploaded can be accessed via link(s) at end of report.

Inspected Facilities

Facility ID: 216884 Type: WELL API Number: 069-06071 Status: PR Insp. Status: EG

Flowline

#1	Type: Non-Well Site	2 of Lines
----	---------------------	------------

Flowline Description

Flowline Type: Non-Well Site Size: 2" Material: Poly
 Variance: Age: Contents: Crude Oil

Integrity Summary

Failures: Spills: Repairs Made:
 Coatings: H2S: Cathodic Protection:

Pressure Testing

Witnessed: Test Result: Charted:

COGCC Rules (check all that apply)

☐ 1101. Installation and Reclamation ☐ 1102. Operations, Maintenance, and Repair ☒ 1103. Abandonment

Comment: Flowline abandonment completed on (2) 2" HDPE (Poly) flowlines; (1) 2" Natural gas flowline and (1) 2" Crude Oil flowline. The flowlines were purged of hydrocarbons (flushed using fresh water) prior to this field inspection. The risers have been removed; both flowlines have been cut and sealed (capped via poly fusion welding) approximately 3'-4' below grade. The flowlines originate and terminate at the same points; at (PA) location 40.630517/-105.04893 and SW side Morningstar Way 40.37875/-105.02956

Corrective Action: Date:

COGCC Comments

Comment	User	Date
Note: There are active flowlines that were observed in the same excavation (near Morningstar Way) as the abandoned flowline endpoints.	maclarej	06/27/2017
Note: Notice of abandonment must be filed with the Commission and with the local governmental designee or local government jurisdiction via COGCC form 42.	maclarej	06/27/2017

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401320954	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4181923
674603414	Capped ends of abandoned flowlines	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4181921
674603416	Capped, Abandoned flowline at well site	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4181922