

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/26/2017

Submitted Date:

06/28/2017

Document Number:

675103691

FIELD INSPECTION FORM

Loc ID 316316 Inspector Name: GRANAHAN, KYLE On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10200
Name of Operator: PETROHUNTER OPERATING COMPANY
Address: 910 SIXTEENTH STREET SUITE 208
City: DENVER State: CO Zip: 80202

Findings:

- 2 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
263059	WELL	TA	02/09/2009	GW	103-10230	BMU 2520	EG

General Comment:

On location to perform 2017 flowline compliance and ensure well is TA - all openings bullplugged/needle valved. 1 - 2" steel flow line with 1 riser - Riser A capped/painted orange/ LOTO; Not able to find riser B at time of work - notified engineering.

Inspected Facilities

Facility ID: 263059 Type: WELL API Number: 103-10230 Status: TA Insp. Status: EG

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: On location to perform 2017 flowline compliance and ensure well is TA - all openings bullplugged/needle valved. 1 - 2" steel flow line with 1 riser - Riser A capped/painted orange/ LOTO; Not able to find riser B at time of work - notified engineering.

Corrective Action:

Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401324755	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4184606