

FORM
INSPRev
X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/28/2017

Submitted Date:

06/30/2017

Document Number:

674901787

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
 _____ Hughes, Jim _____ 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 96705
 Name of Operator: WPX ENERGY PRODUCTION LLC
 Address: P O BOX 3102 MS-25-2
 City: TULSA State: OK Zip: 74101

Findings:

8 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Inspection, WPX	970-263-2716	COGCCInspectionReportsSanJuan@wpxenergy.com	WPX Inspection Mailbox
Ramos, Martha		martha.ramos@state.co.us	
Fischer, Alex		alex.fischer@state.co.us	
Roy, Catherine		catherine.roy@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
427584	PIPELINE	AL	02/03/2012		-	Tiffany Central Delivery Point (CDP)	EI

General Comment:

On June 28, 2017 COGCC SW EPS Jim Hughes conducted a follow up environmental field inspection of the WPX Tiffany Central Delivery Point. For the most recent field inspection report of this facility, please refer to document #674901658.

Location

Lease Road:			
Type	Access		
comment:	Two track dirt road.		
Corrective ActionL		Date:	

Overall Good:

Signs/Marker:			
Type	OTHER		
Comment:	Carsonite pipeline markers.		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	Carsonite pipeline markers list Williams Field Services as the emergency contact.		
Corrective Action:		Date:	

Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	No surface indication of unused equipment belonging to WPX, reported to COGCC SW EPS on 5/11/17 by WPX representatives, remains on location.		
Corrective Action:		Date:	

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:			
Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 427584 Type: PIPELINE API Number: - Status: AL Insp. Status: EI

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches	Pass					

Comment: Corrective Action: Date: **Pits:** NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>On June 28, 2017 COGCC SW EPS Jim Hughes conducted a follow up environmental field inspection of the WPX Tiffany Central Delivery Point. For the most recent field inspection report of this facility, please refer to document #674901658.</p> <p>The pipeline risers and associated equipment related to the WPX Tiffany CDP have been removed. FIRR document #401315419 reports that this was completed on 6/13/17.</p> <p>This facility currently has an "AL" status in the COGIS database. Contact SW Regional Reclamation Specialist Catherine Roy regarding the 1000 series rules and site reclamation.</p>	hughesj	06/30/2017

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401328827	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4187400
674901788	Facility ID #427584 location photo.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4187396
674901789	All WPX risers have been removed from location.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4187397
674901790	No surface indication of risers remains.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4187398