

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/17/2017

Submitted Date:

06/28/2017

Document Number:

680101954

FIELD INSPECTION FORM

Loc ID 399062 Inspector Name: Colby, Lou On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 8220
Name of Operator: BIASI* BRUNO
Address: P O BOX 60
City: BUNKERVILLE State: NV Zip: 89007

Findings:

2 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Colby, Lou		lou.colby@state.co.us	
Williamson, Craig	970-878-3800	cwilliamson@blm.gov	Petroleum Engineer
Thompson, Bud		BLThomps@BLM.gov	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
261676	WELL	PA	07/01/1988	OW	103-40370	WOOSLEY 2	RI

General Comment:

2017 Flowline NTO Inspection 1000' Buffer. There is No visual evidence of equipment (Flowline or Risers) on location. No indication of other facilities identified with aerial imagery assessment.

This Location has received three Action Required Inspections. Equipment, assorted piping, Debris, & Tanks leaking Crude are still on Location. Reclamation Inspection for Location will be submitted seperately from this NTO Inspection.

Inspected FacilitiesFacility ID: 261676 Type: WELL API Number: 103-40370 Status: PA Insp. Status: RI**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401328511	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4187115
680101985	Inspection Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4187110