

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

06/19/2017

Submitted Date:

07/07/2017

Document Number:

690300004**FIELD INSPECTION FORM**
 Loc ID 336550 Inspector Name: Spencer, Stan On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_
**Operator Information:**OGCC Operator Number: 10342Name of Operator: WOODARD\* SANDRA KAddress: 602 OURAY AVENUECity: GRAND JUNCTION State: CO Zip: 81501**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**2 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Woodard, Sandra	970-216-6589	zandi@bresnan.net	
Granahan, Kyle		kyle.granahan@state.co.us	
Fischer, Alex		alex.fischer@state.co.us	
Lujan, Carlos		carlos.lujan@state.co.us	

**General Comment:**

Follow up inspection to assess release observed by Kyle Granahan on 5/10/17 during COGCC Insp # 675103583. Small skid-mounted pumpjack has leaked oil around wellhead. Soil is stained black with strong petroleum odor. Over time, crude oil has been released in an amount greater than one barrel. Operator must submit a Form 19 spill report within 24 hours of receipt of this inspection. Repair pumpjack as necessary to prevent any further release of oil to the environment. Assess nature and extent of contamination with confirmation soil samples. Remediate soil and/or groundwater to COGCC Table 910-1 standards and provide documentation in a either a Supplemental F-19 if cleaned up immediately and/or F-27 if extended remediation of contaminated soil is required. Documentation must include a figure showing spill area with sample locations plus laboratory results.

**Environmental****Spills/Releases:**

Type of Spill: OIL

Estimated Spill Volume: \_\_\_\_\_

Comment: Follow up inspection to assess release observed by Kyle Granahan on 5/10/17 during COGCC Insp # 675103583. Small skid-mounted pumpjack has leaked oil around wellhead. Visible leakage around stuffing box. Soil is stained black with strong petroleum odor.

Corrective Action: Over time, crude oil has been released in an amount greater than one barrel. Operator must submit a Form 19 spill report within 24 hours of receipt of this inspection. Repair pumpjack as necessary to prevent any further release of oil to the environment. Assess nature and extent of contamination with confirmation soil samples. Remediate soil and/or groundwater to COGCC Table 910-1 standards and provide documentation in a either a Supplemental F-19 if cleaned up immediately and/or F-27 if extended remediation of contaminated soil is required. Documentation must include a figure showing spill area with sample locations plus laboratory results.

Date: 07/21/2017

Reportable: \_\_\_\_\_

GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_

Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

Lat \_\_\_\_\_ Long \_\_\_\_\_

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_ Comment: \_\_\_\_\_

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690300005	Pumpjack with oil-stained soil	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4191744">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4191744</a>
690300006	pipe leaks from pumpjack	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4191745">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4191745</a>