



**Photo 1: View of risers at 37.10197, -107.85541, in southeastern portion of the project area.**



**Photo 2: View of the project area from the northeastern corner facing center. Well pad was not recontoured and largely vegetated with weeds.**



**Photo 3: View of the northern portion of the project area from the northeastern corner facing westward. Cut slope is still in place well pad is flat.**



**Photo 4: View of the eastern portion of the project area from the northeastern corner facing southward.**



**Photo 5: View of musk thistles (*Carduus nutans*), approximately 200 growing within the well pad area.**



**Photo 6: View of jointed goatgrass (*Acroptilon repens*), approximately 1000 within the project area.**



**Photo 7: View of the well pad from the access road facing northeastward. Little to no desirable vegetation growing on well pad that is not reclaimed.**