

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/29/2017

Submitted Date:

07/03/2017

Document Number:

681700604

FIELD INSPECTION FORM

Loc ID 318467 Inspector Name: Arauza, Steven On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 46290
Name of Operator: K P KAUFFMAN COMPANY INC
Address: 1675 BROADWAY, STE 2800
City: DENVER State: CO Zip: 80202

Findings:

- 5 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Lara-Mesa, Susana		cogcc@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241346	WELL	PR	04/12/1977	OW	123-09135	AMOCO-CHARTER SCHNEIDER 12	EI

General Comment:

COGCC Environmental inspection of wellhead and pump jack. Well was incapable of production on inspection date: the pump jack belt had been removed; the belt cover was sitting on the side of the pump jack; and power had been shut off to the pumping unit.

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	Operator information on pumpjack sign is faded.		
Corrective Action:	Repair or replace sign to comply with Rule 210.b	Date:	09/03/2017

Emergency Contact Number:

Comment:		Date:	
Corrective Action:			

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Pump jack belt cover is sitting on SW corner of pump jack.		
Corrective Action:	Comply with Rule 603.f using the Rule 603.f guidance document for further details.	Date:	08/03/2017

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type: Ancillary equipment	# 1		corrective date
Comment:	Propane tank plumbed to wellhead has secondary containment device.		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 241346 Type: WELL API Number: 123-09135 Status: PR Insp. Status: EI**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401330674	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4188978
681700612	Well sign with faded operator info.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4188949
681700613	Pump jack belt cover.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4188950
681700614	Inactive wellhead with propane tank.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4188951
681700615	Propane tank with secondary containment.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4188952