

Inspection Photos  
Location Name: USA Shaw 19  
API: 05-081-60020



**Photo 1. Wellhead with no fluid in cellar.**



**Photo 2. Overview of flowline standing at wellhead looking to tank.**



Inspection Photos  
Location Name: USA Shaw 19  
API: 05-081-60020



**Photo 3. Close-up of leak remaining at threads.**



**Photo 4. Close-up of leak and clean-up efforts at threads.**



Inspection Photos  
Location Name: USA Shaw 19  
API: 05-081-60020



**Photo 5. Close-up of leak and clean-up efforts at threads.**



**Photo 6. Close-up of leak and clean-up efforts at threads.**



Inspection Photos  
Location Name: USA Shaw 19  
API: 05-081-60020



**Photo 7. Evidence of clean-up efforts.**



**Photo 8. Close-up of staining at tank.**