



**Photo 1: View of area in the northwestern corner of the well pad that appears to have recently been reclaimed. Revegetation should be monitored here and re-seeding this fall is needed, as poor germination was observed.**



**Photo 2: View of cobble run-down installed since the December 2016 reclamation inspection. Appears to be functioning.**



**Photo 3: View of newly reclaimed area in the southern portion of the project area. Young grass seedlings observed here.**



**Photo 4: View of newly installed cobble-lined diversion in the southwestern portion of the project area. Appears to be functioning.**