

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/10/2017

Submitted Date:

07/11/2017

Document Number:

685303523**FIELD INSPECTION FORM**Loc ID 326166 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10000Name of Operator: BP AMERICA PRODUCTION COMPANYAddress: 380 AIRPORT RDCity: DURANGO State: CO Zip: 81303**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:27 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email | Comment |
|------------------|--------------|---------------------|---------------------------------------|
| Beebe, Sabre | 970-375-7530 | Sabre.Beebe@bp.com | SW Inspection Reports |
| Inspections, All | | SanJuanCOGCC@bp.com | SW Inspection Reports |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 215983 | WELL | PR | 12/28/1999 | GW | 067-07589 | ROY BROWN A 1 | PR |

General Comment:[This inspection does not alliviate requirement to complet any open corrective actions from previous inspections.](#)[See link at end of report for path to downloadable pictures.](#)

Location

| | | | |
|--------------------|------------------------------|-------|--|
| Lease Road: | | | |
| Type | Access | | |
| comment: | Dirt and gravel access road. | | |
| Corrective Action | | Date: | |

Overall Good: ☐

| | | | |
|----------------------|---|-------|--|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | Framed metal sign located at location entrance. | | |
| Corrective Action: | | Date: | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | Freestanding framed sign located at tank. | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐

| | | | | | |
|----------------|------|--------|--|--|--|
| Spills: | | | | | |
| Type | Area | Volume | | | |

In Containment: No

Comment: ☐ Multiple Spills and Releases?

| | | | |
|--------------------|--|-------|--|
| Fencing/: | | | |
| Type | PUMP JACK | | |
| Comment: | Steel mesh safety barrier. | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | Sound walls. | | |
| Corrective Action: | | Date: | |
| Type | OTHER | | |
| Comment: | Telemetry equipment - Stock panel fencing. | | |
| Corrective Action: | | Date: | |
| Type | SEPARATOR | | |
| Comment: | Stock panel fencing. | | |
| Corrective Action: | | Date: | |
| Type | TANK BATTERY | | |
| Comment: | Stock panel fencing. | | |
| Corrective Action: | | Date: | |
| Type | OTHER | | |

| | | | | |
|---------------------------------|--|--|-------|-----------------|
| Comment: | Electrical control panels - Stock panel fencing. | | | |
| Corrective Action: | | | Date: | |
| Equipment: | | | | corrective date |
| Type: Ancillary equipment | # 1 | | | |
| Comment: | Telemetry equipment. | | | |
| Corrective Action: | | | Date: | |
| Type: Vertical Heated Separator | # 1 | | | |
| Comment: | | | | |
| Corrective Action: | | | Date: | |
| Type: Pump Jack | # 1 | | | |
| Comment: | | | | |
| Corrective Action: | | | Date: | |
| Type: Deadman # & Marked | # 4 | | | |
| Comment: | Several markers have been pushed over by livestock and need to be repaired. | | | |
| Corrective Action: | | | Date: | |
| Type: Bird Protectors | # 1 | | | |
| Comment: | | | | |
| Corrective Action: | | | Date: | |
| Type: Other | # 1 | | | |
| Comment: | Sound walls. | | | |
| Corrective Action: | | | Date: | |
| Type: Flow Line | # 1 | | | |
| Comment: | In use - 6" steel line from separator outlet to meter inlet. All lines co-located on location. Operator shall continue to adhere to 2017 Flowline NTO. | | | |
| Corrective Action: | | | Date: | |
| Type: Flow Line | # 1 | | | |
| Comment: | Not in use - 1" steel supply gas line from riser at separator to riser at wellhead. All lines co-located on location. Risers plugged, painted, and tagged for abandonment. Operator shall continue to adhere to 2017 Flowline NTO. | | | |
| Corrective Action: | | | Date: | |
| Type: Flow Line | # 1 | | | |
| Comment: | In use - 6" steel line from wellhead to separator inlet. All lines co-located on location. Operator shall continue to adhere to 2017 Flowline NTO. | | | |
| Corrective Action: | | | Date: | |
| Type: Prime Mover | # 1 | | | |
| Comment: | Electric motor. | | | |
| Corrective Action: | | | Date: | |
| Type: Ancillary equipment | # 1 | | | |
| Comment: | Electrical service equipment. | | | |
| Corrective Action: | | | Date: | |
| Type: Gas Meter Run | # 1 | | | |
| Comment: | | | | |

| | | | |
|---------------------------|-----------|-------|--|
| Corrective Action: | | Date: | |
| Type: Ancillary equipment | # 1 | | |
| Comment: | Wellhead. | | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| | | | | | | |
|--------------------|--|----------|-----------|---------|--------|--|
| Contents | # | Capacity | Type | Tank ID | SE GPS | |
| PRODUCED WATER | 1 | OTHER | PBV STEEL | | , | |
| Comment: | Partially buried 21 BBL steel tank with earthen berms. | | | | | |
| Corrective Action: | | | | | Date: | |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | 21 BBLS | |
| Other (Type) | | |

Berms

| | | | | |
|--------------------|----------|---------------------|---------------------|-------------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Earth | Adequate | Walls Sufficient | Base Sufficient | Adequate |
| Comment: | | | | |
| Corrective Action: | | | Date: | |

Venting:

| | | |
|--------------------|----|-------|
| Yes/No | NO | |
| Comment: | | |
| Corrective Action: | | Date: |

Flaring:

| | |
|--------------------|-------|
| Type | |
| Comment: | |
| Corrective Action: | Date: |

| Inspected Facilities | | | | | | | | | |
|----------------------|---|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 215983 | Type: | WELL | API Number: | 067-07589 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | PR - Review of electronic well file indicates last reported production as April 2017. | | | | | | | | |
| Corrective Action: | | | | | | | | Date: | |

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: Rural residential property.**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND
SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? Pass

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? Pass

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? Pass

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? Pass

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment _____

Corrective Action _____ Date _____

Overall Interim Reclamation**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads _____ Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location ☐ Multi-Well Location ☐

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|--|--------------------------|-----------------------------------|
| Gravel | Pass | Gravel | Pass | | | |
| Compaction | Pass | Compaction | Pass | Material Handling And Spill Prevention | Pass | Berms around produced water tank. |

Comment: [Stormwater BMPs appear to be functioning at time of inspection.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|--|---|
| 685303538 | Wellhead sign. | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4195091 |
| 685303539 | Plugged, painted, and tagged 1" line at wellhead. | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4195092 |
| 685303540 | Plugged, painted, and tagged 1" line at separator. | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4195093 |
| 685303541 | Location overview 1. | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4195094 |
| 685303542 | Location overview 2. | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4195095 |