FORM INSP Rev

X/15

State of Colorado
Oil and Gas Conservation Commission

co

Inspection Date:

07/10/2017

Submitted Date:

07/11/2017

Document Number:

685303524

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109

FIELD INSPECTION FORM

					·		
Loc ID Inspector Name: 325175 St John, William (Cal)			Inspection A Doc Num:		s Summary: HIS IS A FOLLOW UP INSPECTION		
Operator Infor				OLLOW UP INSPECTION REQUIRED			
OGCC Operato	or Number: 96	5705		X	O FOLLOW UP INSPECTION REQUIRED		
Name of Opera	tor: WPX ENERGY	PRODUCTION LLC		<u>Findi</u>	ngs:		
Address: P O BOX 3102 MS-25-2					18Number of Comments 0 Number of Corrective Actions		
City:	TULSA St	ate: OK	Zip:74101	C	 orrective Action Response Requested		
Contact Inform	nation:						
Contact Name	Э	Phone	Email		Comment		
		970-263-2716	COGCCInspectionReport	sSa	WPX Inspection Mailbox		

<u>Inspected</u>	Facilities:

Facility ID	Туре	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214198	WELL	PR	12/01/2010	GW	067-05520	BONDAD 33-9 18	PR

General Comment:

See link at end of report for path to downloadable pictures.

This inspection does not alleviate requirement to complete any open corrective actions from previous inspections.

<u>Location</u>								
Lease Road:								
Туре	Access							
comment:	Dirt and gravel two track road.							
Corrective ActionL				Date:				
Overall Good:								
Signs/Marker:	igns/Marker:							
Туре	WELLHEAD							
Comment:	Metal sign located at gas meter housing.							
Corrective Action:		Date:						
Туре	TANK LABELS/PLACARE	os						
Comment:	Metal sign on tank fencing].						
Corrective Action:				Date				
Emergency Contact N	Number:							
Comment:	Operator contact informat	ion posted on	wellhead.					
Corrective Action:				Date:				
Overall Good:								
Spills:								
Туре	Area	Volume						
Comment:	In Containment: No Comment: Multilple Spills and Releases?							
Fencing/:								
Туре	TANK BATTERY							
Comment:	Steel post and hog wire fe	encing.						
Corrective Action:				Date:				
Туре	SEPARATOR							
Comment:	Concrete barriers.							
Corrective Action:				Date:				
Туре	WELLHEAD							
Comment:	Steel post and pole barrie	er.						
Corrective Action:			Date:					
Equipment:				corrective date				
Type: Bird Protectors	#	1						
Comment:								
Corrective Action: Date:								
Type: Horizontal Hea	ted Separator #	1						
Comment								
Corrective Action:				Date:				

Inspector Name: St John, William (Cal) # 1 Type: Ancillary equipment Comment: Wellhead. Corrective Action: Date: Type: Gas Meter Run # 1 Comment: Corrective Action: Date: # 1 Type: Ancillary equipment Comment: Telemetry equipment. Corrective Action: Date: Type: Flow Line #3 Comment: In use - 2" steel gas flowline from wellhead (A) to separator inlet (B). In use - 2" steel gas sales line from separator outlet (A) to gas meter inlet (B). In use - 1" steel gas line from wellhead (A) to domestic gas tap inlet(B). Operator shall continue to comply with 2017 Flowline NTO. Corrective Action: Date: Type: Other Comment: Cathodic protection equipment. Corrective Action: Date: Tanks and Berms: Contents Tank ID SE GPS Capacity Type PRODUCED WATER 1 **OTHER** Open Top Comment: 125 BBL open top tank with expanded metal cover. Corrective Action: Date: Paint Condition Adequate Other (Content) Other (Capacity) 125 BBLS Other (Type) Berms Permeability (Base) Type Capacity Permeability (Wall) Maintenance Earth Walls Sufficent Base Sufficient Adequate Adequate Comment: Corrective Action: Date: Venting: Yes/No NO Comment: Corrective Action: Date: Flaring: Type Comment:

Corrective Action:	Date:
	,

inspector Na	ine. St J	onn, william (Caij	Inspecte	d Facilities				
Facility ID:	214198	З Туре:	WELL	API Number:	067-05520	Status:	PR	Insp. Status:	PR
				Produc	ing Well			-	
C	omment:	PR - Review	of electronic we	ell file indicates last	reported producti	on as April 20)17.		
Corrective	e Action:							Date:	

	Reclamation - Storm Water - Pit	
Interim Reclamatio	<u>n:</u>	
Date Interim Recl	amation Started: Date Interim Reclamation Completed:	
Land Use:		
Comment: Rura	I residential properties. Farm land and grazing land.	
1002 SITE PREPAR	ATION AND STABILIZATION	
1002a. FENCIN		
Comment		
Corrective Action		Date
1002b. SOIL RE SEGRE		
Comment		
Corrective Action		Date
1002c. PROTE	CTION OF SOILS	
Comment		
Corrective Action		Date
1002E. SURFA	CE DISTRURBANCE MINIMIZATION	
Comment		
Corrective Action		Date
1003a. Waste a	nd Debris removed? Pass	
Comment		
Corrective Action		Date
·	or unneeded equipment onsite? Pass	
Comment		_
Corrective Action		Date
Pit, cel	lars, rat holes and other bores closed? Pass	
Comment		
Corrective Action		Date
Guy line	anchors marked?	
Comment		
Corrective Action		Date

Inspector Name: St John, William (Cal) 1003b. Area no longer in use? Production areas stabilized? 1003c. Compacted areas have been cross ripped? Subsidence over on drill pit? 1003d. Drilling pit closed? Cuttings management: 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? Production areas have been stabilized? Segregated soils have been replaced? RESTORATION AND REVEGETATION Cropland Top soil replaced Perennial forage re-established Recontoured Non-Cropland Recontoured 80% Revegetation Top soil replaced 1003e. INTERIM VEGETATION TRANSECT TRANSECT RESULTS OF DISTURBED AREA% TRANSECT RESULTS OF REFERENCE AREA% TOTAL % OF DESIRABLE VEGETATION COVER VEGETATIVE COVER 1003 f. Weeds Noxious weeds? Comment Corrective Action Overall Interim Reclamation Final Reclamation/ Abandoned Location: Date Final Reclamation Started: Date Final Reclamation Completed: Final Land Use: Reminder: Comment: Pit mouse/rat holes, cellars backfilled Well plugged No disturbance /Location never built Debris removed Contoured Culverts removed Access Roads Regraded Gravel removed Locations, facilities, roads, recontoured Location and associated production facilities reclaimed Compaction alleviation Dust and erosion control Cropland: perennial forage Non cropland: Revegetated 80% Weeds present _____ Subsidence ____ 1004.d. FINAL VEGETATION TRANSECT TRANSECT RESULTS OF DISTURBED AREA% TRANSECT RESULTS OF REFERENCE AREA% TOTAL % OF DESIRABLE VEGETATION COVER VEGETATIVE COVER Comment: Corrective Action: Well Release on Active Location Overall Final Reclamation Multi-Well Location

		/				
Storm Water:						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	Berms around produced water tank.
Gravel	Pass	Gravel	Pass			
Comment: Stormwater BMPs appear to be functioning at time of inspection. Corrective Action: Date:						Date:
Pits: X NO SURFACE INDICATION OF PIT						

Attached Documents

You can go to COGCC Images (https://cogcc.state.co.us/weblink/) and search by document number:

Document Num	Description	URL		
685303543	Wellhead sign.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4195096		
685303544	Location overview 1.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4195097		
685303545	Location overview 2.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4195098		

Date Run: 7/11/2017 Doc [#685303524]