

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/27/2017

Submitted Date:

07/05/2017

Document Number:

674704146**FIELD INSPECTION FORM**Loc ID 312427 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10150Name of Operator: BLACK HILLS PLATEAU PRODUCTION LLCAddress: 1515 WYNKOOP ST STE 500City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Danahue, Jessica	(720) 210-1333	jessica.donahue@blackhillsco rp.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
221576	WELL	PR	03/22/1981	GW	077-08178	FEDERAL SHIRE-GULCH 35-1	PR

**General Comment:**

2017 Flowline NTO Inspection 1000' Buffer  
Shadowing Operator Pressure Testing Team

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	TRASH		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

## Inspected Facilities

Facility ID: 221576 Type: WELL API Number: 077-08178 Status: PR Insp. Status: PR

## Producing Well

Comment: Producing well

Corrective Action:

Date:

## Flowline

#1 Type: Well Site

1 of Lines

## Flowline Description

Flowline Type: Well Site

Size: 2"

Material: Carbon Steel

Variance:

Age:

Contents:

## Integrity Summary

Failures:

Spills:

Repairs Made:

Coatings:

H2S:

Cathodic Protection:

## Pressure Testing

Witnessed: Yes

Test Result: Pass

Charted:

## COGCC Rules(check all that apply)

☐ 1101. Installation and Reclamation

☒ 1102. Operations, Maintenance, and Repair

☐ 1103. Abandonment

Comment:

Corrective Action:

Date:

#2 Type: Sales Line

1 of Lines

## Flowline Description

Flowline Type: Sales Line

Size:

Material:

Variance:

Age:

Contents:

## Integrity Summary

Failures:

Spills:

Repairs Made:

Coatings:

H2S:

Cathodic Protection:

## Pressure Testing

Witnessed: Yes

Test Result: Pass

Charted:

## COGCC Rules(check all that apply)

☐ 1101. Installation and Reclamation

☒ 1102. Operations, Maintenance, and Repair

☐ 1103. Abandonment

Comment:

Corrective Action:

Date:

#3 Type: Dump Line

1 of Lines

## Flowline Description

Flowline Type: Dump Line

Size: 2"

Material: Carbon Steel

Variance:

Age:

Contents:

## Integrity Summary

Failures:

Spills:

Repairs Made:

Coatings:

H2S:

Cathodic Protection:

**Pressure Testing**Witnessed: YesTest Result: Pass

Charted:

**COGCC Rules(check all that apply)**☐ 1101. Installation and Reclamation☒ 1102. Operations, Maintenance, and Repair☐ 1103. Abandonment

Comment:

Corrective Action:

Date:

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401332888	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4190736">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4190736</a>