



photo 1: Facing west at the beginning of the former access road.



photo 2: The access road has been reclaimed since the previous inspection. There is wood mulch covering the reclaimed area.



photo 3: Facing north along the reclaimed access road toward the location.



photo 4: The electric utility box remains at the east side of the reclaimed access road.



photo 5: Facing north toward the location.



photo 6: Facing west at the location.



photo 7: Facing west at the tank battery site. There is an area of subsidence and the orange safety fence is not maintained.



photo 8: There is List B noxious weeds (Diffuse knapweed) growing at the location.