

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/05/2017

Submitted Date:

07/13/2017

Document Number:

673715704

FIELD INSPECTION FORM

Loc ID 317077 Inspector Name: Sherman, Susan On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10495
Name of Operator: LILIS ENERGY INC
Address: 300 E SONTERRA BLVD SUITE 1220
City: SAN ANTONIO State: TX Zip: 78258

Findings:

- 5 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Nanke, Kevin	(303) 618-4507	knanke@lilisenergy.com	
Blackwell, Seth	(210) 999-5400	sblackwell@lilisenergy.com	EVP-Land & BD

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
235877	WELL	SI	05/15/2013	OW	121-08367	PIEPER LEO 3-29	PA

General Comment:

[Operator is to contact landowner when fencing is installed for reclamation.](#)

Inspected Facilities

Facility ID: 235877 Type: WELL API Number: 121-08367 Status: SI Insp. Status: PA

Cement

Cement Contractor

Contractor Name: Ranger Contractor Phone: _____

Surface Casing

Cement Volume (sx): _____ Circulate to Surface: YES
 Cement Fall Back: _____ Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____ Good Return During Job: _____

Production Casing

Cement Volume (sx): _____ Good Return During Job: _____

Plugging Operations

Depth Plugs(feet range): 4847, 3850, 500 Cement Volume (sx): 264

Good Return During Job: YES Cement Type: 15.8 ppg

Comment: Brand X from Sterling, CO was wireline truck on location.
 Fluid level @ 3000', 68 bbls to load hole. Plugging orders followed except CICR for 3850' plug was set at 3765 (vs 3750') and 180 (vs 150) sxs were pumped for surface plug.
 Twenty-two sxs of cement were pumped from 50' to surface (see attached photos of cut, cap and cover of wellhead).

Corrective Action: _____ Date: _____

Workover

Comment: Ranger Rig 206

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment _____

Corrective Action _____

Date _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: In pasture. Stock pond ~400' east of well. There are 8 Y-W poles set in pasture from CR 32 to well. Site is under a Form 27 to close pits, equipment is still present and flowlines need to be abandoned.

Well plugged Pass Pit mouse/rat holes, cellars backfilled Pass

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment: _____

Corrective Action: _____

Date _____

Overall Final Reclamation In Process Well Release on Active Location Multi-Well Location

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
673715713	Lilis Pieper Leo 3-29 PA	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4196372
673715726	Lilis Pieper Leo 3-29 PA CCC	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4196373