

Inspection Photos

Location Number: 450561



Photo 1 Culvert at entrance from north



Photo 2 Stormwater detention on northeast corner from northwest

Inspection Photos



Photo 3 Sound mitigation bales on south and southeast corner of location.



**Photo 4 Pete Martin R-12 rig
Welding of rat hole casing underway from east.**