



Photo 1: View from the northeastern portion of the project area facing center.



Photo 2: View of the northern portion of the project area from the northeastern corner facing westward.



Photo 3: View of new stormwater controls installed in head-cut area at culvert outlet.



Photo 4: View of damaged culvert inlet at the well pad entrance.