



Photo 1: View of Russian knapweed plants growing within the southern portion of the project area.



Photo 2: View of musk thistles within the northwestern corner of the project area.



Photo 3: View of area of access road that was recently repaired.



Photo 4: Another view of the repaired access road.