Inspector Name: Trujillo, Aaron

FORM INSP Rev

X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/11/2017

Submitted Date:

07/11/2017

Document Number:
682502387

FIELD INSPECTION FORM

Loc ID	Inspector Nan	ne:	On-Site In	spection	St	tatus	Summary:		
329457 Trujillo, Aaron			2A	2A Doc Num:		THIS IS A FOLLOW UP INSPECTION			
Operator Inf	ormation:				×	FO	LLOW UP INSPECTION REQ	UIRED	
OGCC Oper	ator Number:	100322				NO FOLLOW UP INSPECTION REQUIRED			
Name of Ope	erator: NOBLE EN	NERGY IN	C		<u>Fi</u>	Findings:			
A -l -l 4.0		OTF 0000				4	Number of Comments		
Address: 16	325 BROADWAY	STE 2200				0 Number of Corrective Actions			
City:	DENVER	State:	CO	Zip: 80202	<u> </u>	Cor	— rrective Action Response Requeste	ed	
Contact Info	Contact Information:								
Contact Name Phone			е	Email			Comment		
Binschus, Chris				chris.binschus@state.co.us					
,				NBL_DJBU_Inspections@NB LENERGY.COM			All Inspections		
Inspected Facilities:									
Facility ID	Туре	Status	Status Date	Well Class	API Num		Facility Name	Insp Status	
249585	WELL	PA	06/19/2014	SI	123-17388		MEYER B 2-9	RI	

General Comment:

2017 Flowline NTO Inspection 1000' Buffer (or statewide). This is also a follow-up, Reclamation Inspection for PA Well API#123-17388 to inspection doc. #682400968. Well was plugged #8/27/2013

Inspector Name: Trujillo, Aaron **Location** Overall Good: **Emergency Contact Number:** Comment: Corrective Action: Date: Overall Good: Spills: Туре Area Volume In Containment: No Comment: Multilple Spills and Releases? **Equipment:** corrective date Type: Flow Line Comment: 2017 Flowline NTO Inspection 1000' Buffer (or statewide). No visual evidence of equipment on location. No indication of other facilities identified with aerial imagery assessment. Corrective Action: Date: Venting: Yes/No Comment: Corrective Action: Date: Flaring: Туре Comment: Corrective Action: Date:

Inspector Name: Trujillo, Aaron

				Inspecte	d Facilities				
acility ID: _	249585	Type:	WELL	API Number:	123-17388	Status: _	PA	Insp. Status:	RI

Inspector Name: Trujillo, Aaron

Reclamation - Storm Water - Pit							
Interim Reclamatio	<u>n:</u>						
Date Interim Recl	amation Started: Date Interim Reclamation Completed:						
Land Use:							
Comment:							
1002 SITE PREPAR	ATION AND STABILIZATION						
1002a. FENCIN	G						
Comment							
Corrective Action		Date					
1002b. SOIL RE SEGRE							
Comment							
Corrective Action		Date					
1002c. PROTEC	CTION OF SOILS						
Comment							
Corrective Action		Date					
1002E. SURFA	CE DISTRURBANCE MINIMIZATION						
Comment							
Corrective Action		Date					
1003a. Waste a	nd Debris removed?						
Comment							
Corrective Action		Date					
ļ	or unneeded equipment onsite?						
Comment		_					
Corrective Action		Date					
Pit, cel	lars, rat holes and other bores closed?						
Comment							
Corrective Action		Date					
Guy line	anchors marked?						
Comment							
Corrective Action		Date					

Inspector Name: Trujillo, Aaron Production areas stabilized? 1003b. Area no longer in use? 1003c. Compacted areas have been cross ripped? Subsidence over on drill pit? 1003d. Drilling pit closed? Cuttings management: 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? Production areas have been stabilized? Segregated soils have been replaced? RESTORATION AND REVEGETATION Cropland Top soil replaced Perennial forage re-established Recontoured Non-Cropland Recontoured 80% Revegetation Top soil replaced 1003e. INTERIM VEGETATION TRANSECT TRANSECT RESULTS OF DISTURBED AREA% TRANSECT RESULTS OF REFERENCE AREA% TOTAL % OF DESIRABLE VEGETATION COVER VEGETATIVE COVER 1003 f. Weeds Noxious weeds? Comment Corrective Action Overall Interim Reclamation Final Reclamation/ Abandoned Location: Date Final Reclamation Started: Date Final Reclamation Completed: Final Land Use: Reminder: Comment: Pit mouse/rat holes, cellars backfilled Well plugged No disturbance /Location never built Debris removed Access Roads Regraded Contoured Culverts removed Gravel removed Location and associated production facilities reclaimed Locations, facilities, roads, recontoured Compaction alleviation Dust and erosion control Cropland: perennial forage Non cropland: Revegetated 80% Weeds present _____ Subsidence ____ 1004.d. FINAL VEGETATION TRANSECT TRANSECT RESULTS OF DISTURBED AREA% TRANSECT RESULTS OF REFERENCE AREA% TOTAL % OF DESIRABLE VEGETATION COVER VEGETATIVE COVER _____ Comment:

Inspection Doc. #682400968 indicated crop at location was not reflective of the reference area as crop on the disturbance area (~20 inches) appeared stunted when compared to the reference area (~50 inches). Inspection required operator to perform additional reclamation. Crop growth over the disturbance area appears to have improved, however crop growth still appears to be stunted (~48 inches) when compared to crop on the reference area (~72 inches). This concern is being forwarded to Weld County Reclamation Specialist Chris Binschus. Corrective Action: Date	Inspector Name: Tr	rujillo, Aaron						
Overall Final Reclamation Well Release on Active Location Multi-Well Location Attached Documents You can go to COGCC Images (https://cogcc.state.co.us/weblink/) and search by document number: Document Num Description URL 401338019 INSPECTION SUBMITTED http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4194858	•	Inspection Doc. #682400968 area as crop on the disturbar reference area (~50 inches). Crop growth over the disturbar appears to be stunted (~48 ir inches). This concern is being	Date					
Attached Documents You can go to COGCC Images (https://cogcc.state.co.us/weblink/) and search by document number: Document Num Description URL 401338019 INSPECTION http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4194858 SUBMITTED	Corrective Action:							
You can go to COGCC Images (https://cogcc.state.co.us/weblink/) and search by document number: Document Num Description URL 401338019 INSPECTION http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4194858 SUBMITTED								
Document Num Description URL 401338019 INSPECTION SUBMITTED LITERATE URL http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4194858	Attached Docum	<u>nents</u>						
401338019 INSPECTION SUBMITTED http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4194858	You can go to CC	OGCC Images (https://cogcc	c.state.co.us/weblink/) and search by document number:					
SUBMITTED	Document Num	Description	URL					
682502388 Inspection Photos http://ogccweblink.state.co.us/DownloadDocumentPDE.aspx2DocumentId=4194848			http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?Doc	umentId=4194858				
	682502388	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?Doc	umentId=4194848				