

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/11/2017

Submitted Date:

07/11/2017

Document Number:

689500005**FIELD INSPECTION FORM**
 Loc ID 335946 Inspector Name: GRANAHAH, KYLE On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 100264Name of Operator: XTO ENERGY INCAddress: PO BOX 6501City: ENGLEWOOD State: CO Zip: 80155**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:19 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Dooling, Jessica		Jessica_Dooling@xtoenergy.com	Piceance Creek insp
Reid, Van		van_reid@xtoenergy.com	Piceance Creek insp
Kardos, Kelly		kelly_kardos@xtoenergy.com	Piceance Creek insp

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
286172	WELL	PR	10/01/2012	GW	103-10867	PICEANCE CREEK UNIT 297-11A5	PR
286173	WELL	PR	11/06/2009	GW	103-10866	PICEANCE CREEK UNIT 297-11A4	PR
286174	WELL	PR	03/15/2011	GW	103-10865	PICEANCE CREEK UNIT 297-11A3	WK
286175	WELL	PR	05/29/2009	GW	103-10864	PICEANCE CREEK UNIT 297-11A2	PR
286176	WELL	PR	06/10/2009	GW	103-10863	PICEANCE CREEK UNIT 297-11A1	PR
286177	WELL	PR	07/17/2009	GW	103-10862	PICEANCE CREEK UNIT 297-11A6	PR
286178	WELL	PR	05/27/2009	GW	103-10861	PICEANCE CREEK UNIT 297-11A9	PR
286179	WELL	PR	06/10/2009	GW	103-10860	PICEANCE CREEK UNIT 297-11A8	PR
286180	WELL	PR	03/15/2011	GW	103-10859	PICEANCE CREEK UNIT 297-11A7	PR

General Comment:

Canary swab rig on location - clean tubing and put back on line

LocationOverall Good: ☒

Signs/Marker:			
Type	CONTAINERS		
Comment:	Present/complete		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Present/complete		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Present/complete		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 970-675-4117

Corrective Action:

Date: _____

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Horizontal Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 3		
Comment:	Chem tote w/secondary containment		
Corrective Action:		Date:	
Type: Plunger Lift	# 9		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No NO

Comment:			
Corrective Action:		Date:	
Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

--	--	--	--

Inspected Facilities						
Facility ID:	286172	Type:	WELL	API Number: 103-10867	Status: PR	Insp. Status: PR
Producing Well						
Comment:	PR - via plunger lift; no leaks/venting. Remote pressure monitoring present.					
Corrective Action:						Date:
Facility ID:	286173	Type:	WELL	API Number: 103-10866	Status: PR	Insp. Status: PR
Producing Well						
Comment:	PR - via plunger lift; no leaks/venting. Remote pressure monitoring present.					
Corrective Action:						Date:
Facility ID:	286174	Type:	WELL	API Number: 103-10865	Status: PR	Insp. Status: WK
Workover						
Comment:	Canary swab rig on location - clean out tubing and put back on line; plunger getting caught up around 3100'.					
Corrective Action:						Date:
Facility ID:	286175	Type:	WELL	API Number: 103-10864	Status: PR	Insp. Status: PR
Producing Well						
Comment:	PR - via plunger lift; no leaks/venting. Remote pressure monitoring present.					
Corrective Action:						Date:
Facility ID:	286176	Type:	WELL	API Number: 103-10863	Status: PR	Insp. Status: PR
Producing Well						
Comment:	PR - via plunger lift; no leaks/venting. Remote pressure monitoring present.					
Corrective Action:						Date:
Facility ID:	286177	Type:	WELL	API Number: 103-10862	Status: PR	Insp. Status: PR
Producing Well						
Comment:	PR - via plunger lift; no leaks/venting. Remote pressure monitoring present.					
Corrective Action:						Date:
Facility ID:	286178	Type:	WELL	API Number: 103-10861	Status: PR	Insp. Status: PR
Producing Well						
Comment:	PR - via plunger lift; no leaks/venting. Remote pressure monitoring present.					
Corrective Action:						Date:
Facility ID:	286179	Type:	WELL	API Number: 103-10860	Status: PR	Insp. Status: PR
Producing Well						
Comment:	PR - via plunger lift; no leaks/venting. Remote pressure monitoring present.					

Corrective Action:		Date:	
Facility ID: 286180 Type: WELL API Number: 103-10859 Status: PR Insp. Status: PR			
Producing Well			
Comment:	PR - via plunger lift; no leaks/venting. Remote pressure monitoring present.		
Corrective Action:		Date:	

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND
SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____ Pass _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____ Pass _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____ Pass _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____ Pass _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____ Pass _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment _____

Corrective Action _____ Date _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads _____ Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location ☐ Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass					
Berms	Pass					
Retention Ponds	Pass					
Gravel	Pass					

Comment: [No sediment flow evident](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401338095	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4194970